Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED OMB No. 1004-0135 Expires show ember 50, 2000

BUREAU OF LAND MANAGEMENT	5. Lease Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS	NM-58878
Do not use this form for proposals to drill or reenter an	6. If Indian, Allottee or Tribe Name
abandoned well. Use Form 3160-3 (APD) for such proposals.	
SUBMIT IN TRIPLICATE – Other instructions on reverse side	7. If Unit or CA/Agreement, Name and/or N
Type of Well	
Oil Well Gas Well Other	8. Well Name and No.
. Name of Operator	Federal L #1
Epic Energy, LLC	9. API Well No.
a. Address 3b. Phone No. (include area code)	30-043-20825
415 East Main, Farmington, NM 87402 505-327-4892	10. Field and Pool, or Exploratory Area
Location of Well (Footage, Sec., T., R., M., or Survey Description)	Alamito Gallup
90' FSL & 1765' FEL; Section 28, T23N, R7W	11. County or Parish. State
	Sandoval, NM
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, R	EPORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION	
Alter Casing Fracture Treat Reclamat	on (Start/Resume) Water Shut-Off tion Well Integrity
Subsequent Report	
	rily Abandon
Final Abandonment Notice Convert to Injection Plug Back Water Di	
3 Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of a lf the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM BlA. Required Completion of the involved operations. If the operation results in a multiple completion or recompletion in Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including recladermined that the site is ready for final inspection.)	ired subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once amation, have been completed, and the operator has
Based on well performance, suspect that there is a hole in the casing. Epic Energy, LLC, is preperforations and then isolate the hole(s) in the casing and design a cement squeeze based on the RBP will be removed and the well will be returned to production.	
	AUG 1 6 2019
	DISTRICT III
Thereby certify that the foregoing is true and correct	
Name (Printed Typed) Title	
Name (Printed Typed) Title	neering & Operations
Name (Printed Typed) Title	
Name (Printed Typed) John C. Thompson Signature Date Title VP of Engir	
Name (Printed Typed) John C. Thompson Signature Date	neering & Operations
Name (Printed Typed) John C. Thompson Signature Date THIS SPACE FOR FEDERAL OR STATE USE	neering & Operations
Name (Printed Typed) John C. Thompson Signature Date THIS SPACE FOR FEDERAL OR STATE USE	neering & Operations

