	UNITED STATES EPARTMENT OF THE IN UREAU OF LAND MANAG			FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018			
SUNDRY Do not use thi		5. Lease Serial No. NMSF078596					
abandoned we	II. Use form 3160-3 (APL	D) for such p	proposals.		6. If Indian, Allottee		
SUBMIT IN T	TRIPLICATE - Other inst	ructions on	page 2		7. If Unit or CA/Agr 14080011152	eement, N	Name and/or No.
 Type of Well ☐ Oil Well	ner				8. Well Name and No MADDOX COM		
2. Name of Operator HILCORP ENERGY COMPAN	Contact:	SHORTY		9. API Well No. 30-045-29856-00-S1			
3a. Address 1111 TRAVIS STREET HOUSTON, TX 77002		e. (include area code) 24-5188		10. Field and Pool or Exploratory Area BLANCO MESAVERDE			
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)		11. County or Parish, State				
Sec 17 T30N R8W SWSW 91 36.805973 N Lat, 107.705432			SAN JUAN COUNTY, NM			NM	
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OT	HER D	ATA
TYPE OF SUBMISSION			TYPE OF	FACTION			
Notice of Intent	□ Acidize	Dee Dee		□ Product	ion (Start/Resume)	_	ater Shut-Off
□ Subsequent Report	 Alter Casing Casing Repair 		raulic Fracturing	Recomp			/ell Integrity
Final Abandonment Notice	□ Change Plans	_	g and Abandon		arily Abandon		
pt	Convert to Injection	🗖 Plug	g Back	U Water D	Disposal		
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Hilcorp Energy Company requests permission to recomplete the subject well in the Fruitland Coal and downhole commingle with the existing Mesaverde formation. Attached is the procedure, wellbore diagram, plat,gas capture plan, and interim reclamation plan. A pre-interim reclamation site inspection was completed by Bob Switzer, BLM, on 8/23/2019. A DHC application will be filed and approved prior to commingling. A closed loop system will be used.							
	C104 FOR DHC		Notify NMOCD 24 h prior to beginning operations			OCT	1 1 2019
HOLD	C104 1 0.					STRI	CT III
14. I hereby certify that the foregoing is true and correct. Electronic Submission #480441 verified by the BLM Well Information System For HILCORP ENERGY COMPANY, sent to the Farmington Committed to AFMSS for processing by ALBER A WETHINGTON on 09/03/2019 (19AMW0583SE) Name (Printed/Typed) PRISCILLA SHORTY							
Signature (Electronic S	Date 08/26/20	010					
	THIS SPACE FO			SE			
						Ι	
_Approved By_JOE KILLINS	TitleENGINEER Date 10/10/2019						
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent which would entitle the applicant to condu	Office Farming	ton					
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							
(Instructions on page 2) ** BLM REVISED **							
		F	\sim				~

R

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

Form C-102 August 1, 2011 Permit 271539

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number	2. Pool Code	3. Pool Name
30-045-29856	71629	BASIN FRUITLAND COAL (GAS)
4. Property Code	5. Property Name	6. Well No.
319187	MADDOX COM	001B
7. OGRID No.	8. Operator Name	9. Elevation
372171	HILCORP ENERGY COMPANY	5800

10. Surface Location Section Township Range Lot Idn Feet From N/S Line Feet From E/W Line County UL - Lot SAN JUAN 17 30N 08W 915 660 W Μ S

11. Bottom Hole Location If Different From Surface										
UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County	
12. Dedicated Acres 320.00			13. Joint or Infill		14. Consolida	14. Consolidation Code			15. Order No.	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

	OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.
	E-Signed By: Priscilla Shorty Title: Operations Regulatory Tech - Sr. Date: 8/26/2019
•	SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.
	Surveyed By: Neale Edwards
	Date of Survey: 12/28/1998
	Certificate Number: 6857




HILCORP ENERGY COMPANY MADDOX COM 1B FRUITLAND COAL RECOMPLETION SUNDRY

	API #:		3004	4529856					
					105				
1	NMOCD	Contact	OCD 24 br	prior to MI		B PROCEDURES rd and document all casing pressures <u>daily</u> , including BH, IC (if present)			
2	BLM					nd HEC safety and environmental regulations.			
1.	. MIRU service rig and associated equipment; NU and test BOP.								
2.	TOOH with 2-3/8" tubing set at 5,038'.								
3.	PU a 4-1/2" cast iron bridge plug and RIH with work string; set CIBP at +/- 3,270' to isolate the existing Mesa Verde formation.								
4.	 Load wellbore with fluid. RU pressure test truck. Perform a Mechanical Integrity Test on wellbore. Chart record the MIT test (Notify NMOCD +24hr before actual test). Review and submit the MIT test results to the NMOCD. If the MIT fails, discuss with both the NMOCD on a plan of action to remediate the wellbore. Perform 2nd MIT once remediated. 								
5.	4-1/2" TOC at li squeeze work n			0/22/1999, p	roposed pe	erfs from 2,002'-2,552'. Cement to surface on 7" intermediate casing string. No			
6.	PU a 7" cast irc	n bridge p	plug and RIF	H with work s	string; set Cl	IBP at +/- 2,600' to isolate the liner top and provide a base for the frac.			
7.	Top off the casi	ng with flu	uid and pres	sure test the	casing to a	t least frac pressure, but not more than 80% of casing yield strength.			
		Weakest	casing is 7"	J-55 20#/ft.	Maximum te	est pressure = 0.8 x 3740 psi = 2,992 psig.			
8.	. N/D BOP, N/U frac stack and test frac stack to frac pressure. RDMO service rig.								
9.	RU E-line crew. Perforate the Fruitland Coal. (Top perforation @ 2,002', Bottom perforation @ 2,552').								
10.	RU stimulation crew. Frac the Fruitland Coal in one or two stages. (Top perforation @ 2,002', Bottom perforation @ 2,552').								
11.	RIH and set a final 7" plug at +/- 1955' to isolate the frac.								
12.	MIRU service rig. Nipple down frac stack, nipple up BOP and test.								
13.	. Clean out to the top of the first isolation plug at +/- 1955'. Drill out the plug.								
14.	. Clean out to the top of the second isolation plug at +/- 2,600'. When water and sand rates are acceptable, drill out the plug.								
15.	. Clean out the wellbore to top of MV isolation plug at 3,270'. When water and sand rates are acceptable, drill out the plug.								
16.	Clean out to PBTD at 5,097'. TOOH and lay down milling and cleanout assembly.								
17.	TIH and land 2-3/8" production tubing. Get a commingled Fruitland/Mesa Verde flow rate.								
	All formation to	ps have b	een reviewe			the Maddox Com 1B. The proposed formation tops agree e NMOCD website.			



HILCORP ENERGY COMPANY MADDOX COM 1B FRUITLAND COAL RECOMPLETION SUNDRY



Hilcorp Energy Interim Reclamation Plan **Maddox Com #1B** API: 30-045-29856 M – Sec.17-T030N-R008W Lat: 36.80588, Long: -107.70473 Footage: 915' FSL & 660' FWL San Juan County, NM

1. PRE- INTERIM RECLAMATION SITE INSPECTION

1.1) A pre-interim reclamation site inspection was completed by Bob Switzer with the BLM and Chad Perkins construction Foreman for Hilcorp Energy on August 23, 2019.

2. LOCATION INTERIM RECLAMATION PROCEDURE

- 2.1) Interim reclamation work will be completed after well recompletion in the fall of 2019 or spring of 2020.
- 2.2) Location tear drop will be re-defined as applicable during interim reclamation.
- 2.3) All disturbed areas will be seeded, any disturbed areas that are compacted will be ripped before seeding.
- 2.4) All trash and debris will be removed within 50' buffer outside of the location disturbance during reclamation.

3. ACCESS ROAD RECLAMATION PROCEDURE:

3.1) No lease access road issues were identified at the time of onsite.

4. SEEDING PROCDURE

- 4.1) A Pinion/Juniper seed mix will be used for all reclaimed and disturbed areas of the location.
- 4.2) Drill seeding will be done where applicable and all other disturbed areas will be broadcast seeded and harrowed, broadcast seeding will be applied at a double the rate of seed.
- 4.3) Timing of the seeding will take place when the ground is not frozen or saturated.

5. WEED MANAGEMENT

5.1) No action is required at this time for weed management, no noxious weeds were identified during the onsite.

