Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY	5. Lease Serial No. NMSF080670							
Do not use the	is form for proposals to II. Use form 3160-3 (AP	drill or to re	enter an		6. If Indian, Allottee or	Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreen 8910010540	ment, Name and/or No.		
Type of Well					8. Well Name and No. SAN JUAN 27-4 U	NIT 51		
					9. API Well No. 30-039-20149-00)-S1		
3a. Address 1111 TRAVIS STREET HOUSTON, TX 77002 3b. Phone No. (include area code) Ph: 505-324-5161					10. Field and Pool or Exploratory Area BASIN DAKOTA			
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)			11. County or Parish, State			
Sec 29 T27N R4W SENE 145 36.547363 N Lat, 107.266983					RIO ARRIBA CO	UNTY, NM		
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	ER DATA		
TYPE OF SUBMISSION			ТҮРЕ О	FACTION				
Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Product	ion (Start/Resume)	☐ Water Shut-Off		
_	☐ Alter Casing	☐ Hyd	raulic Fracturing	□ Reclam	ation	■ Well Integrity		
☐ Subsequent Report	☐ Casing Repair	□ New	Construction	Recomp Re	olete	☐ Other		
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug	and Abandon	☐ Tempor	arily Abandon			
BP	☐ Convert to Injection	Plug	Back	☐ Water I	Disposal			
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi Hilcorp Energy Company plan commingle the existing Dakots schematic. The DHC applicati system will be utilized. Interim	rk will be performed or provide operations. If the operation resondonment Notices must be filial inspection. s to recomplete the subject formation. Attached is the on will be submitted and a	the Bond No. or sults in a multiple ed only after all ect well in the ne MV C102, approved prior	n file with BLM/BIA e completion or reco requirements, includ Mesaverde form recomplete proc r to commingling	Required submpletion in a sing reclamation and dedure & well. A closed I	bsequent reports must be f new interval, a Form 3160 n, have been completed an ownhole Ilbore	iled within 30 days -4 must be filed once		
system will be dillized. Interim	reciamation will be penol	illied alter su	sadill som	NMO(0			
				NOV 14	2019			
	HOLD C104 FOR	DHC	D	ISTRIC				
14. I hereby certify that the foregoing is	Electronic Submission #4	NERGY COMP	ANY, sent to the	Farmington	•			
Name (Printed/Typed) ETTA TRU	JJILLO		Title OPERA	TIONS REC	BULATORY TECH SE	?		
Signature (Electronic S	Submission)		Date 11/08/2	019				
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE			
_Approved_By_JOHN_HOFFMAN			TitlePETROLE	UM ENGINI	EER	Date 11/14/20		
certify that the applicant holds legal or equ	nditions of approval, if any, are attached. Approval of this notice does not warrant tify that the applicant holds legal or equitable title to those rights in the subject leas ich would entitle the applicant to conduct operations thereon.				Office Farmington			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Office Farmington

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 **District II**

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
1220 S. St Francis Dr. Santa Fe. NM

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 273913

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-039-20419	2. Pool Code 72319	3. Pool Name BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code	5. Property Name	6. Well No.
319210	SAN JUAN 27 4 UNIT	051
7. OGRID No.	8. Operator Name	9. Elevation
372171	HILCORP ENERGY COMPANY	6884

10. Surface Location

ı	UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County	
ı	н	29	27N	04W		1450	N	800	E	RIO A	RRIBA
1										100 /	

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated	Acres 0.00 E/2		13. Joint or Infill		14. Consolidatio	n Code		15. Order No.	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

	(<u>*</u> .)

OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Etta Trujillo

Title: Operations/Regulatory Tech Sr

Date: 11/08/2019

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

Russell H McNeace

Date of Survey:

6/25/1968

Certificate Number:

1500



HILCORP ENERGY COMPANY SAN JUAN 27-4 UNIT 51 MESA VERDE RECOMPLETION SUNDRY

JOB PROCEDURES

- MIRU service rig and associated equipment; test BOP. Check bradenhead pressures daily and record throughout the recomplete project. Notify NMOCD and BLM of any anomalous pressure changes.
- 2. TOOH with 2-3/8" tubing set at 8,154'.
- 3. Set a 4-1/2" plug at +/- 7,895' to isolate the Dakota.
- 4. Load the hole and perform MIT (Pressure test to 560 psi). Notifiy NMOCD and BLM +/-24hr prior to testing (and in the event of a failed test).
- 5. RU W/L. Run CBL, record TOC.
- 6. Set a 4-1/2" plug at +/- 6,500'.
- 7. Load the hole and pressure test casing.
- 8. N/D BOP, N/U frac stack and pressure test frac stack.
- 9. Perforate and frac the Mesaverde formation (Top Perforation @ 5,400'; Bottom Perforation @ 6,350').
- 10. If needed, isolate frac stages with a plug.
- 11. Nipple down frac stack, nipple up BOP and test.
- 12. TIH with a mill and drill out any plugs above the Dakota isolation plug.
- 13. Clean out to Dakota isolation plug.
- 14. Drill out Dakota isolation plug and cleanout to PBTD of 8,169'. TOOH.
- 15. TIH and land production tubing. Get a commingled Dakota/Mesaverde flow rate.



HILCORP ENERGY COMPANY SAN JUAN 27-4 UNIT 51 MESA VERDE RECOMPLETION SUNDRY

