Form 3160-5 (June 2015)

1 . 1

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

	D	Ore	L/2 L	00.			1417 11	47 1	OLIV	LLITT		
SUNDR'	Υ	NC	IT	CE	S	AND	REF	0	RTS	ON	WELLS	6

5. Lease Serial No. NMSF079074

Do not use th	is form for proposals to drill	or to re-enter an					
abandoned we	6. If Indian, Allottee	If Indian, Allottee or Tribe Name					
SUBMIT IN	TRIPLICATE - Other instruct	ions on page 2	7. If Unit or CA/Agr 891000538B	eement, Name and/or No.			
Type of Well	ner		8. Well Name and No. SAN JUAN 30-6 UNIT 144				
Name of Operator HILCORP ENERGY COMPAR	Contact: ETT/ NY E-Mail: ettrujillo@hilcorp		9. API Well No. 30-039-26132-00-S1				
3a. Address 1111 TRAVIS STREET HOUSTON, TX 77002		Phone No. (include area code): 505-324-5161	10. Field and Pool or LA JARA PICT	Exploratory Area URED CLIFFS			
4. Location of Well (Footage, Sec., 7	C., R., M., or Survey Description)		11. County or Parish	, State			
Sec 27 T30N R7W SWSW 86 36.778766 N Lat, 107.564534			RIO ARRIBA C	COUNTY, NM			
12. CHECK THE AI	PPROPRIATE BOX(ES) TO I	INDICATE NATURE O	F NOTICE, REPORT, OR OT	HER DATA			
TYPE OF SUBMISSION		TYPE OF	ACTION				
Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/Resume)	■ Water Shut-Off			
	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity			
☐ Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete	Other			
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	☐ Temporarily Abandon	Subsurface Commingli			
68	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal				
test for data recording. The Fr formation. Attached is the FC	uests permission to perforate F uitland Coal will be commingle C102, procedure and current/p ind approved prior to comming	ed with existing Pictured Coroposed wellbore schem	Cliffs				
HOLD C104 FOR	DHC Density Exception		NMOCD OCT 23 20	019			
14. Therefore exists that the formation is			DISTRICT	+			
14. I hereby certify that the foregoing is	Electronic Submission #48860	BY COMPANY, sent to the	Farmington	The state of the s			
Name (Printed/Typed) ETTA TRU	JJILLO	Title OPERA	Title OPERATIONS/REGULATORY TECH SR				
Signature (Electronic S	Submission)	Date 10/17/20	019				
	THIS SPACE FOR F	EDERAL OR STATE (OFFICE USE				
_Approved_By_JOHN_HOFFMAN_ Conditions of approval, if any, are attached certify that the applicant holds legal or equ	d. Approval of this notice does not w	arrant or	UM ENGINEER	Date 10/18/2019			
which would entitle the applicant to condu	act operations thereon.	Office Farmingt					
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a crime statements or representations as to any	for any person knowingly and matter within its jurisdiction.	willfully to make to any department or	r agency of the United			

PV

5

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone: (505) 334-6178 Fax: (505) 334-6170 **District IV** 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico **Energy, Minerals and Natural** Resources **Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

Form C-102 August 1, 2011

Permit 273544

WELL LOCATION AND ACREAGE DEDICATION PLAT

· · · · · · · · · · · · · · · · · · ·								
1. API Number	2. Pool Code	3. Pool Name						
30-039-26132	71629	BASIN FRUITLAND COAL (GAS)						
4. Property Code	5. Property Name	6. Well No.						
318716	SAN JUAN 30 6 UNIT	144						
7. OGRID No.	8. Operator Name	9. Elevation						
372171	HILCORP ENERGY COMPANY	6907						


10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County	ı
М	27	30N	07W		865	l s	815	l w	RÍO ARRIBA	l

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County	
	12. Dedicated Acres 320.00 W/2		13. Joint or Infill		14. Consolidation Code			15. Order No.		

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Etta Trujillo

Operations/Regulatory Tech Sr Title:

Date: 10/17/2019

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

Neale C. Edwards

Date of Survey:

12/17/1998

Certificate Number:




HILCORP ENERGY COMPANY SAN JUAN 30-6 UNIT 144 Fruitland Coal Layer Pressure Test SUNDRY

JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP. Check bradenhead pressures daily and record throughout the recomplete project. Notify NMOCD and BLM of any anomalous pressure changes.
- 2. TOOH with 2-3/8" tubing set at 3,821'.
- 3. RIH and set CIBP at +/-3,760'. NOTE: CBL run 5/26/1999 shows good cement from PBTD up to 810'.
- Load the hole and perform MIT (Pressure test to 560 psi) in 4-1/2" csg above the CIBP set @ 3,760". Notifiy NMOCD and BLM +/-24hr prior to testing (and in the event of a failed test).
- 4. TIH w/ workstring to new PBTD @ +/-3,760*.
- 5. PU workstring and blow well dry. TOOH w/ workstring.
- 6. RIH w/ perf assembly and perforate the following depths/intervals: 3,581' to 3,748'. RD WL.
- 7. TIH w/ workstring and blow well dry, wait 30-60 minutes and attempt to blow well dry again to confirm minimal water influx.
- RIH w/ RBP and tandem DHPG's, set at 3,741'. Repeat process setting subsequent RBP's with tandem gauges at 3,733', 3,718', 3,709', 3,692', 3,684', 3,620' and 3,578'. RD WL.
- 9. RBIH w/ production tubing with RBP retrieving tool on end. ND BOP, NU and test WH.
- 10. RDMO rig while waiting for buildup data.
- 11. MIRU service rig and associated equipment; test BOP. Check bradenhead pressures daily and record throughout the recomplete project. Notify NMOCD and BLM of any anomalous pressure changes.
- 12. Commence pulling RBP's with tubing.
- 12. RIH w/ bit and drill out CIBP @ +/-3,760'.
- 13. RIH w/ production tubing and land tubing at +/-3,821*.
- 14. Ensure barriers are holding. ND BOP and BOP equipment. NU and test WH.
- 15. RDMO location.



HILCORP ENERGY COMPANY SAN JUAN 30-6 UNIT 144 Fruitland Coal Layer Pressure Test SUNDRY





HILCORP ENERGY COMPANY **SAN JUAN 30-6 UNIT 144**

Fruitland Coal Layer Pressure Test SUNDRY

