Form 3160-5 (June 2015)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018

Eureau of Land III No. N0613101841

	RY NOTICES AND REF his form for proposals	PORTS ON WELLS s to drill or to re-enter an	6. If Indian, Allot	tee or Tribe Name	
		(APD) for such proposals			
SUBMIT IN TRIPLICATE - Other instructions on page 2  1. Type of Well  Gas Well  Other  2. Name of Operator				7. If Unit of CA/Agreement, Name and/or No. NMNM 135216A  8. Well Name and No. W Lybrook Unit 710H  9. API Well No.	
			9. API Well No.		
Enduring Resources Iv LLC  3a. Address  3b. Phone No. (include a			30-045-35803	l or Exploratory Area	
200 Energy Court Farmington NM 87401		505-636-9743		Lybrook Mancos W	
4. Location of Well (Footage, Sec., T.R.M., or Survey Description) SHL: 1961' FNL & 2464' FWL Sec 13 T23N R9W Unit: F BHL: 706' FNL & 2284' FEL Sec 11 T23N R9W Unit: B		1)	11. Country or Pa San Juan, NM	11. Country or Parish, State San Juan, NM	
12	CHECK THE APPROPRIATE	BOX(ES) TO INDICATE NATURE	OF NOTICE, REPORT OR	OTHER DATA	
TYPE OF SUBMISSION		TYP	E OF ACTION		
□Notice of Intent	Acidize	Deepen	Production(Start/Resume	) Water ShutOff	
	Alter Casing	☐ Hydraulic Fracturing	Reclamation	☐ Well Integrity	
Subsequent Report	Casing Repair	■ New Construction	Recomplete	☑Other *	
Final Abandonment Notice	Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	No Flare	
	Convert to Injection	☐Plug Back	☐Water Disposal		
directionally or recomplete horizont provide the Bond No. on file with B completion or recompletion in a new reclamation, have been completed a	ally, give subsurface locations and m BLM/BIA. Required subsequent repo w interval, a Form 3160-4 must be fi	neasured and true vertical depths of all per orts must be filed within 30 days following filed once testing has been completed. Fina	tinent markers and zones. Attach to g completion of the involved oper	imate duration thereof If the proposal is to det the Bond under which the work will be perfonr ations. If the operation results in a multiple filed only after all requirements, including	
directionally or recomplete horizont provide the Bond No. on file with B completion or recompletion in a new reclamation, have been completed a is ready for final inspection.)	ally, give subsurface locations and m BLM/BIA. Required subsequent repo w interval, a Form 3160-4 must be fi and the operator has detennined that	neasured and true vertical depths of all per orts must be filed within 30 days following filed once testing has been completed. Fina	tinent markers and zones. Attach is g completion of the involved oper al Abandonment Notices must be	the Bond under which the work will be perfon ations. If the operation results in a multiple filed only after all requirements, including	
directionally or recomplete horizont provide the Bond No. on file with B completion or recompletion in a new reclamation, have been completed a is ready for final inspection.)	ally, give subsurface locations and m BLM/BIA. Required subsequent repo w interval, a Form 3160-4 must be fi and the operator has detennined that	neasured and true vertical depths of all per orts must be filed within 30 days following filed once testing has been completed. Find the site	tinent markers and zones. Attach is g completion of the involved oper al Abandonment Notices must be	the Bond under which the work will be perfon ations. If the operation results in a multiple filed only after all requirements, including	
directionally or recomplete horizont provide the Bond No. on file with B completion or recompletion in a new reclamation, have been completed a is ready for final inspection.)	ally, give subsurface locations and m BLM/BIA. Required subsequent repo w interval, a Form 3160-4 must be fi and the operator has detennined that	neasured and true vertical depths of all per orts must be filed within 30 days following filed once testing has been completed. Find the site	tinent markers and zones. Attach is g completion of the involved oper al Abandonment Notices must be	the Bond under which the work will be perfont ations. If the operation results in a multiple filed only after all requirements, including 601H/502H/507H/510H.	
directionally or recomplete horizont provide the Bond No. on file with B completion or recompletion in a new reclamation, have been completed a is ready for final inspection.)  Tring was not necessary during the complete description of the complete descr	ally, give subsurface locations and m BLM/BIA. Required subsequent repo w interval, a Form 3160-4 must be fi and the operator has detennined that i	neasured and true vertical depths of all per orts must be filed within 30 days following ided once testing has been completed. Find the site	tinent markers and zones. Attach is g completion of the involved oper al Abandonment Notices must be	the Bond under which the work will be perfont ations. If the operation results in a multiple filed only after all requirements, including 501H/502H/507H/510H.	
directionally or recomplete horizont provide the Bond No. on file with B completion or recompletion in a new reclamation, have been completed a is ready for final inspection.)  ing was not necessary during the been completed a increase of the beautiful or the b	ally, give subsurface locations and m BLM/BIA. Required subsequent report winterval, a Form 3160-4 must be fil and the operator has detennined that the g the time of stimulation act and the structure of stimulation act and g is true and correct. Name (P)	neasured and true vertical depths of all per orts must be filed within 30 days following ided once testing has been completed. Find the site	tinent markers and zones. Attach is geompletion of the involved oper al Abandonment Notices must be standard on the Nageezi Unit 5	the Bond under which the work will be perfont ations. If the operation results in a multiple filed only after all requirements, including 601H/502H/507H/510H.	
directionally or recomplete horizont provide the Bond No. on file with B completion or recompletion in a new reclamation, have been completed a is ready for final inspection.)  Ting was not necessary during the complete description of the complete description of the complete description. I hereby certify that the foregoing the complete description of the complete	ally, give subsurface locations and m BLM/BIA. Required subsequent report winterval, a Form 3160-4 must be fil and the operator has detennined that the g the time of stimulation act and the structure of stimulation act and g is true and correct. Name (P)	neasured and true vertical depths of all per ports must be filed within 30 days following ided once testing has been completed. Find the site.  tivity for the frac activity for Enc	tinent markers and zones. Attach is geompletion of the involved oper al Abandonment Notices must be standard on the Nageezi Unit 5	the Bond under which the work will be perfont ations. If the operation results in a multiple filed only after all requirements, including 601H/502H/507H/510H.  NMOCD	
directionally or recomplete horizont provide the Bond No. on file with B completion or recompletion in a new reclamation, have been completed a is ready for final inspection.)  Tring was not necessary during the complete that the foregoing was grantled to the complete that the foregoing was formally the foregoing was formally that the foregoing was formally the foregoing was for the foregoing was for the foregoing was fo	ally, give subsurface locations and m BLM/BIA Required subsequent repo winterval, a Form 3160-4 must be fi and the operator has detennined that i g the time of stimulation act and is true and correct. Name (P)	neasured and true vertical depths of all per orts must be filed within 30 days following ided once testing has been completed. Find the site tivity for the frac activity for Enc crinted/Typed)  Title: Permit Sp	ecialist	the Bond under which the work will be perfont ations. If the operation results in a multiple filed only after all requirements, including 601H/502H/507H/510H.  NMOCD	
directionally or recomplete horizont provide the Bond No. on file with B completion or recompletion in a new reclamation, have been completed a is ready for final inspection.)  Tring was not necessary during the been completed a ceep Granillo.	ally, give subsurface locations and m BLM/BIA. Required subsequent report interval. a Form 3160-4 must be fixed the operator has detennined that the operator has detennined that the string of the time of stimulation act	rinted/Typed)  Title: Permit Sp  Date: 10/9/18  TEFOR FEDERAL OR ST	ecialist	the Bond under which the work will be perfont ations. If the operation results in a multiple filed only after all requirements, including 601H/502H/507H/510H.  NMOCD	

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.