Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS					5. Lease Serial No. JIC77			
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					If Indian, Allottee or Tribe Name JICARILLA APACHE			
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agree	ment, Name and/or No.		
Type of Well					8. Well Name and No. AXI APACHE A 11			
Name of Operator DJR OPERATING LLC Contact: ALICE MASCARENAS E-Mail: amascarenas@djrllc.com					9. API Well No. 30-039-22914-00)-S1		
3a. Address 1600 BROADWAY SUITE 160 DENVER, CO 80202		3b. Phone No. (include area code) Ph: 505.632.3476		10. Field and Pool or E BALLARD	xploratory Arca			
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description	n)			11. County or Parish, S	tatc		
Sec 15 T23N R5W NESW 180			RIO ARRIBA CO	OUNTY, NM				
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
TYPE OF SUBMISSION			TYPE OF	ACTION				
☐ Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Product	ion (Start/Resume)	☐ Water Shut-Off		
	☐ Alter Casing	□ Нус	Iraulic Fracturing	☐ Reclam	ation	■ Well Integrity		
Subsequent Report	☐ Casing Repair	□ Nev	v Construction	☐ Recomp	olete	Other		
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug	g and Abandon	☐ Tempor	arily Abandon			
bl.	☐ Convert to Injection	□ Plug	g Back	☐ Water I	Disposal			
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. This subject well as P&A'd on 12/23/19 per attached EOW Report, plugged wellbore diagram and marker.								
JAN 1 0 2020 DISTRICT								
14. I hereby certify that the foregoing is true and correct.								
	Electronic Submission # For DJR O		d by the BLM Wel C, sent to the Rio		n System			
Committed to AFMSS for processing by JOE KILLINS on 01/09/2020 (20JK0004SE)								
Name (Printed/Typed) ALICE MA	ASCARENAS		Title REGUL	ATORY TE	CHNICIAN			
Signature (Electronic Submission) Date 01/07/2020								
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved By ACCEPTED				JOE KILLINS TitlePETROLEUM ENGINEER Date 01/09/20		Date 01/09/2020		
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct the applicant the appl	Office Rio Puer	co						
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United								

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.





DJR Operating LLC PO Box 156 Bloomfield, NM 87413

P.O. Box 1979, Farmington, NM 87499 (505) 325-2627 Name: AXI Apache A 11 API:30-039-22914

Well Plugging Report

Work Detail

12/20/2019

Load supplies. Travel to location.

Pre-trip equipment. Travel to new location.

Spot equipment. RU unit & pumping equipment.

CHECK PSI: TBG-0#, CSG-0#, BH-0#. Open well to the pit.

Kill well with 20 bbls of fresh water. ND WH, Strip on BOP. RU Rig floor & TBG equipment

X-over TBG equipment. LD 69 JTS of 1" EUE + 1 JT 1.25" EUE.

RU A+ WL. RIH with gauge ring tag @ 1636'. LD gauge ring. Attempt a smaller OD gauge ring tag @ same depth. UNABLE TO SET CIBP. NMOCD REP Brandon Powell APPROVED TO SPOT INSIDE PLUG without CIBP. Waiting on BLM approval.

X-over TBG equipment. Pick up 1.25" pipe. RIH to 2072'. SIW. SDFD.

Clean & secure location.

Travel back to yard.

12/23/2019

Load supplies. Travel to location.

JSA. Service & start equipment.

CHECK PSI: TBG-0#, CSG-0#, BH-0#. Open well to the pit.

EST CIRC with 5 bbls of fresh water. Pump 15 total. PLUG 1 APPROVED BY BLM REP MARK DECKER, WOC 4 HRS.

PLUG #1 (PC/FRUITLAND/KIRTLAND/OJO ALAMO) 2071' - 1505'. M&P 16 SKS @ 2 % CAL, 1.15 yield, 15.8ppg, 18.4cu/ft, 3.2 bbls slurry. Displace with fresh water. LD TOC. TOOH. WOC 4 HRS.

Wait on cement sample. TIH tag TOC @ 1621'. EST CIRC with 5 bbls. Pressure test casing to 500# PSI, held OK.

PLUG #1A (OJO ALAMO) 1621' - 1338'. M&P 8 SKS, 1.15 yield, 15.8ppg, 9.2u/ft, 1.6 bbls slurry. Displace with fresh water. LD TOC. LD TBG to surface plug. PLUG #2 NACIMIENTO/SURFACE) 344' - 0'. M&P 10 SKS, 1.15 yield, 15.8ppg, 11.5cu/ft, 2 bbls slurry. CIRC cement to surface. LD all TBG.

RD rig floor and TBG equipment. ND BOP, NU WH.

Cut & remove WH. Find TOC @ 35' inside 2-7/8". Find TOC @ in 7" @ 29 . Weld & install DHM @ 36*, 13', 19" N / 107*, 21', 6" W. TOP OFF DHM with 25 sks of Class G cement.

RD unit & pumping equipment.

Clean & secure location. MOL

Travel back to yard.

Comments

Date	dot	Comment
	PLUG #1	PLUG #1 (PC/FRUITLAND/KIRTLAND/OJO ALAMO) 2071' - 1505'. M&P 16 SKS @ 2 % CAL, 1.15 yield, 15.8ppg, 18.4cu/ft, 3.2 bbls slurry. Displace with fresh water. LD TOC. TOOH. WOC 4 HRS.
	PLUG #1A	PLUG #1A (OJO ALAMO) 1621' - 1338'. M&P 8 SKS, 1.15 yield, 15.8ppg, 9.2u/ft, 1.6 bblslry. Displace with fresh water. LD TBG to surface plug.
	PLUG #2	PLUG #2 (NACIMIENTO/SURFACE) 344' - 0'. M&P 10 SKS, 1.15 yield, 15.8ppg, 11.5cu/ft, 2 bbls slurry. CIRC cement to surface. LD all TBG.
	DHM CORD	Weld & install DHM @ 36*, 13', 19" N / 107*, 21', 6" W.

On Site Reps:

Name	Association	Notes
Mark Decker	BLM	Not on location
Mark Decker	BLM	On location

AXI Apache A 11 As Plugged 12/23/19

Ballard Pictured Cliffs 1800' FSL, 1790' FWL, Section 15, T-23-N, R-5-W Rio Arriba County, NM, API #30-039-22914

Top off surface w/25 sxs

Today's Date: 2/14/19

Spud: 4/4/82

Completed: 7/17/82 Elevation: 6733' GI

6741' KB

9-7/8" hole

Nacimiento @ 294'


Ojo Alamo @ 1600'

Kirtland @ 1830'

Fruitland @ 1932'

Pictured Cliffs @ 2121'

6.25" Hole



PBTD 2194' TD 2260'

Cement circulated to surface

7" 23# Casing set @ 95' Cement with 59cf, circulated

> Plug #2: 344' - 0' Class G cement, 10 sxs Tag TOC @ 35' in 2-7/8" csg And 29' in 7" casing.

Plug #1A: 1621' - 1338' Class G cement, 8 sxs

Plug #1: 2071' - 1505' Class G cement, 16 sxs w/ 2% CaCl2; tag low at 1621'.

Note: Unable to set CIBP in casing.

Pictured Cliffs Perforations: 2121' - 2148'

2.875", 6.5#, Casing set at 2234' Cement with 609 cf; circulated 9 sxs to surface

