5 10 11 12 13 74 75			
Form 3160-3 JUN 2006 (September 2001)		OMB	M APPROVED No. 1004-0136 January 31, 2004
UNITED STAT		5. Lease Serial No.	
DEPARTMENT OF THE BUREAU OF LAND MAN		AM 8 22 NMSF-0787	
APPLICATION FOR PERMIT TO		6. If Indian, Allott	ee or Tribe Name
<u> </u>	REGE	7. If Unit or CA A	greement, Name and No.
la. Type of Work: DRÏLL REEN	OTO FARMI	Rosa Unit	NMNM-078407A-MV
1b. Type of Well: Oil Well Gas Well Other	Single Zone Multip	8. Lease Name and 129C	Weil No.
2. Name of Operator		9. API Well No.	0 0000
Williams Production Company, LLC	3b. Phone No. (include area code)	30 -03	39-29883
3a. Address P.O. Box 640 Aztec, NM 87410	(505) 634-4208	Blanco Mesa	• •
4. Location of Well (Report location clearly and in accordance with a		11. Sec., T., R., M.,	or Blk. and Survey or Area
At surface 1730' FSL & 2030' FWL K			
At proposed prod. zone 2325' FNL & 1660' FWL 214. Distance in miles and direction from nearest town or post office.	*	Section 34, 3	
approximately 18 miles northeast of Navajo City, New M		Rio Arriba	NM NM
15. Distance from proposed* location to nearest	16. No. of Acres in lease	17. Spacing Unit dedicated to the	
property or lease line, ft. (Also to nearest drig, unit line, if any) 1730	2,561,86	320.0 (W/2)	
18. Distance from proposed location*	19. Proposed Depth	20. BLM/BIA Bond No. on file	
to nearest well, drilling, completed, applied for, on this lease, ft. 1600'		UT0847	
21. Elevations (Show whether DF, KDB, RT, GL, etc.)	22. Approximate date work will st		ition
6,361' GR	June 1, 2006 24. Attachments	1 month	
 Well plat certified by a registered surveyor. A Drilling Plan. A Surface Use Plan (if the location is on National Forest System SUPO shall be filed with the appropriate Forest Service Office 	Item 20 above). 5. Operator certification	pecific information and/or plan	· ·
25. Signature	Name (Printed/Typed)		Date
Title	Larry Higgins		4/17/2006
Drilling COM 1			
Approved by (Signature)	Name (Printed/Typed)		Date / O of
Title	Office		1000
Application approval does not warrant or certify that the applicant ho operations thereon. Conditions of approval, if any, are attached.	lds legal or equitable title to those rights in	the subject lease which would en	title the applicant to conduct
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, mal		d willfully to make to any departm	nent or agency of the United
States any false, fictitious or fraudulent statements or representations *(Instructions on reverse)	as to any matter within its jurisdiction.		
Williams Exploration and Production Company, LLC, proposes	to drill a wall to dayalan the Plance I	leasurande formation at the she	vo dopovihod logation in
accordance with the attached drilling and surface use plans.	to drill a well to develop the blanco ly	esaverue formation at the abo	ve described location in
The surface is under jurisdiction of the Bureau of Reclamation	, with federal minerals administered by	the BLM, Farmington Field Of	ffice.
This location has been archaeologically surveyed La Plata Arc	chaeological Consultants. Copies of the	eir report have been submitted	directly to the BLM.
This APD is also serving as an application to obtain pipeline rig	ghts-of-way. A 101.0-foot pipeline tie	would be required for this locat	iion.
	HOLDON	por dination	ral survey
		Alepa	
DR	RILLING OPERATIONS AUTHORIZED AR	e ville	GD
SH	BLIEFT TO COUNTY IANGE WITH ACTION	·	

DRILLING OPERATIONS AUTHORIZED ARE SUBJECT TO COMPLIANCE WITH ATTACHED "GEAERAL REQUIREMENTS".

Q

District I PO Box 1980, Hobbs, NM 88241-1980

State of New Mexico Energy, Minerals & Natural Resources Department

OIL CONSERVATION DIVISION

Form C-102 Revised February 21, 1994 Instructions on back

District II PO Drawer DD, Artesia, NM 88211-0719

Submit to Appropriate District Office Fee Lease - 4 Copies State Lease - 4 Copies

District III 1000 Rio Brazos Rd., Aztec, NM 87410

District IV PO Box 2088, Santa Fe, NM 87504-2088

'API Number

320.0 Acres - (W/2)

¹² Dedicated Acres

PO Box 2088 Santa Fe, NM 87504-2088 APR 19 AM 8 RECEIVED AMENDED REPORT

¹⁵ Order No.

OTO FARMINGTON NM

Pool Name

WELL LOCATION AND ACREAGE DEDICATION PLAT


30.0	39-6	29883		72319 BLANCO MESAVERDE						
*Property	Code			*Property Name *Well Number						11 Number
1703	3-/	212	ROSA UNIT COM 129C						129C	
OGRID N	OGRID No. Operator Name Elevation						levation			
12078	2			WILLIAMS PRODUCTION COMPANY 5361					6361'	
<u> </u>	¹⁰ Surface Location									
UL or lot no.	Section	Township	Range						County	
K	34	32N	6W		1730 SOUTH 2030 WES					RIO ARRIBA
	¹¹ Bottom Hole Location If Different From Surface									
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/Wes	t line	County RIO
F	34	32N	6W	N 2325 NORTH 1660 WEST R.						ADDTRA

Pool Code

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION


⁵⁴ Consolidation Code

¹³ Joint or Infill



Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resour	rces May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II	OIL CONSERVATION DIVISION	ON 30-039-29883
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.	5. Indicate Type of Lease FEDERAL X
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE
District IV	Salita Fe, Nivi 67303	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		NMSF-078772
	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	
	CATION FOR PERMIT" (FORM C-101) FOR SUCH	Rosa Unit
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well 🛛 Other	8. Well Number 129C
2. Name of Operator	Cas well & Care	9. OGRID Number 120782
Williams Production Company, LL	C	7. OGRAD TUMBON 120702
3. Address of Operator		Blanco Mesaverde
P.O. Box 640 Aztec, NM 87410		
4. Well Location		
Į.	trans the court line and 2020 feet from the sure	41:
	from the south line and 2030 feet from the wes	
Section 34 Townshi		MPM County Rio Arriba
100	11. Elevation (Show whether DR, RKB, RT,	GR, etc.)
Di Di La La La La Casa	6,361' GR	
Pit or Below-grade Tank Application 🛛 o		
Pit typereserve_Depth to Groundwate	er_>100'_Distance from nearest fresh water well_>1,	000'_Distance from nearest surface water>1,000'
Pit Liner Thickness: 12 mil Below-	Grade Tank: Volumebbls; Con	struction Material
12. Check A	Appropriate Box to Indicate Nature of I	Notice, Report or Other Data
12. Chock i	ippropriate Bon to mareate reading of	records, resport of Suidi Butu
MOTIOE OF IN	TENTION TO:	CURCEOUENT REPORT OF
NOTICE OF IN	I ENTION TO.	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		AL WORK
	PLUG AND ABANDON REMEDI	
PERFORM REMEDIAL WORK	PLUG AND ABANDON ☐ REMEDI CHANGE PLANS ☒ COMME	AL WORK ALTERING CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON	AL WORK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	PLUG AND ABANDON	AL WORK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OTHER:	PLUG AND ABANDON	AL WORK ALTERING CASING NCE DRILLING OPNS. P AND A CEMENT JOB CETAILS, and give pertinent dates, including estimated date
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: 13. Describe proposed or compost of starting any proposed wo	PLUG AND ABANDON	AL WORK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OTHER:	PLUG AND ABANDON	AL WORK ALTERING CASING NCE DRILLING OPNS. P AND A CEMENT JOB CETAILS, and give pertinent dates, including estimated date
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: 13. Describe proposed or compost of starting any proposed wo	PLUG AND ABANDON	AL WORK ALTERING CASING NCE DRILLING OPNS. P AND A CEMENT JOB CETAILS, and give pertinent dates, including estimated date
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: 13. Describe proposed or compost of starting any proposed wo	PLUG AND ABANDON	AL WORK ALTERING CASING NCE DRILLING OPNS. P AND A CEMENT JOB CETAILS, and give pertinent dates, including estimated date
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compost of starting any proposed we or recompletion.	PLUG AND ABANDON	AL WORK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compof starting any proposed we or recompletion. Drilling/Completion pit to be located to the proposed with the proposed we have a second proposed with the proposed w	PLUG AND ABANDON	AL WORK ALTERING CASING NCE DRILLING OPNS. PAND A CEMENT JOB CEasily, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion nead. Pit multi-use drilling and completion to avoid
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compof starting any proposed we or recompletion. Drilling/Completion pit to be located additional site disturbance and pit.	PLUG AND ABANDON	AL WORK ALTERING CASING NCE DRILLING OPNS. PAND A CEMENT JOB CEasily, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion nead. Pit multi-use drilling and completion to avoid oduction tubing set. Pit to be constructed,
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compof starting any proposed we or recompletion. Drilling/Completion pit to be located additional site disturbance and pit.	PLUG AND ABANDON	AL WORK ALTERING CASING NCE DRILLING OPNS. PAND A CEMENT JOB CEasily, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion nead. Pit multi-use drilling and completion to avoid oduction tubing set. Pit to be constructed,
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compof starting any proposed we or recompletion. Drilling/Completion pit to be located additional site disturbance and pit.	PLUG AND ABANDON	AL WORK ALTERING CASING NCE DRILLING OPNS. PAND A CEMENT JOB CEasily, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion nead. Pit multi-use drilling and completion to avoid oduction tubing set. Pit to be constructed,
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compof starting any proposed we or recompletion. Drilling/Completion pit to be located additional site disturbance and pit.	PLUG AND ABANDON	AL WORK ALTERING CASING NCE DRILLING OPNS. PAND A CEMENT JOB CEasily, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion nead. Pit multi-use drilling and completion to avoid oduction tubing set. Pit to be constructed,
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compof starting any proposed we or recompletion. Drilling/Completion pit to be located additional site disturbance and pit.	PLUG AND ABANDON	AL WORK ALTERING CASING NCE DRILLING OPNS. PAND A CEMENT JOB CEasily, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion nead. Pit multi-use drilling and completion to avoid oduction tubing set. Pit to be constructed,
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compof starting any proposed we or recompletion. Drilling/Completion pit to be located additional site disturbance and pit.	PLUG AND ABANDON	AL WORK ALTERING CASING NCE DRILLING OPNS. PAND A CEMENT JOB CEasily, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion nead. Pit multi-use drilling and completion to avoid oduction tubing set. Pit to be constructed,
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compof starting any proposed we or recompletion. Drilling/Completion pit to be local additional site disturbance and pid operated and closed in accordance.	PLUG AND ABANDON	AL WORK ALTERING CASING NCE DRILLING OPNS. P AND A CEMENT JOB CETAILS, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion needd. Pit multi-use drilling and completion to avoid oduction tubing set. Pit to be constructed, procedures.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compof starting any proposed we or recompletion. Drilling/Completion pit to be local additional site disturbance and pid operated and closed in accordance.	PLUG AND ABANDON	AL WORK ALTERING CASING NCE DRILLING OPNS. PAND A CEMENT JOB CEasily, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion nead. Pit multi-use drilling and completion to avoid oduction tubing set. Pit to be constructed,
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compof starting any proposed we or recompletion. Drilling/Completion pit to be local additional site disturbance and pit operated and closed in accordance or proposed and closed in accordance or proposed with the information of the proposed with the	PLUG AND ABANDON	AL WORK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compof starting any proposed we or recompletion. Drilling/Completion pit to be local additional site disturbance and pid operated and closed in accordance.	PLUG AND ABANDON	AL WORK ALTERING CASING NCE DRILLING OPNS. PAND A CEMENT JOB CETAILS, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion need. Pit multi-use drilling and completion to avoid oduction tubing set. Pit to be constructed, procedures.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. Drilling/Completion pit to be located additional site disturbance and pit operated and closed in accordance or accordance of the proposed with the information of the proposed with	PLUG AND ABANDON	AL WORK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. Drilling/Completion pit to be located additional site disturbance and pit operated and closed in accordant operat	PLUG AND ABANDON	AL WORK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. Drilling/Completion pit to be located additional site disturbance and pit operated and closed in accordance or accordance of the proposed with the information of the proposed with	PLUG AND ABANDON	AL WORK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. Drilling/Completion pit to be local additional site disturbance and properated and closed in accordance of the proposed with the information of the property of the proposed we or recompletion.	PLUG AND ABANDON	AL WORK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. Drilling/Completion pit to be located additional site disturbance and pit operated and closed in accordant operat	PLUG AND ABANDON	AL WORK

WILLIAMS PRODUCTION COMPANY ROSA UNIT #129C 1730' FSL & 2030' FWL, SECTION 34, T32N, R6W, NMPM RIO ARRIBA COUNTY, NEW MEXICO ELEVATION: 6361'





WILLIAMS PRODUCTION COMPANY

Operations Plan

(Note: This procedure will be adjusted on site based upon actual conditions)

DATE:

4/12/2006

FIELD:

Blanco MV

WELL NAME:

Rosa #129C

Rio Arriba, NM

SURFACE:

BLM

BH LOCATION:

SENW Sec 34-32N-6W

MINERALS:

BLM

SURF LOCATION:

NESW Sec 34-32N-6W

ELEVATION:

6.361' GR

LEASE #

SF-078772

MEASURED DEPTH: 6,402'

I. GEOLOGY:

Surface formation - San Jose

A. FORMATION TOPS: (KB)

Name	TVD	MD	Name	TVD	MD
Ojo Alamo	2,350	2,618	Cliff House	5,380	5,730
Kirtland	2,460	2,749	Menefee	5,420	5,770
Fruitland	2,880	3,215	Point Lookout	5,600	5,950
Picture Cliffs	3,140	3,486	Mancos	5,910	6,260
Lewis	3,455	3,805	TD	6,050	6,402

- B. MUD LOGGING PROGRAM: none
- C. LOGGING PROGRAM: Cased Hole Logs only
- D. NATURAL GAUGES: Gauge any noticeable increases in gas flow. Record all gauges in Tour book and on morning reports.

II. DRILLING:

- A. MUD PROGRAM: Clear water with benex to 7" casing point. Convert to a LSND mud to log and run pipe. Treat for lost circulation as necessary. Obtain 100% returns prior to cementing. Notify Engineering of any mud losses. Use air w/Air Hammer from 7 in. csg.to TD.
- B. BOP TESTING: While drill pipe is in use, the pipe rams and the blind rams will be function tested once each trip. The anticipated reservoir is expected to be less than 1300 psi, so the BOPE will be tested to 250 psi (Low) for 5 minutes and 1500 psi (High) for 10 minutes. Utilize a BOPE Testing Unit with a recording chart and appropriate test plug for testing. The drum brakes will be inspected and tested each tour. All tests and inspections will be recorded in the tour book as to time and results.

III. MATERIALS

A. CASING PROGRAM:

CASING TYPE	HOLE SIZE	<u>DEPTH</u> (MD)	CASING SIZE	WT. & GRADE
Surface	12-1/4"	+/- 300'	9-5/8"	36# K-55
Intermediate	8-3/4"	+/- 4,002°	7"	20# K-55
Prod. Liner	6-1/4"	+/- 3,902'-6,402'	4-1/2"	10.5# K-55

B. FLOAT EQUIPMENT:

- 1. <u>SURFACE CASING:</u> 9-5/8" notched regular pattern guide shoe. Run (1) standard centralizer on each of the bottom (3) joints of Surface Casing.
- 2. INTERMEDIATE CASING: 7" cement nose guide shoe with a self-fill insert float. Place float collar one joint above the shoe. Install (1) Turbulent centralizer on each of the bottom (3) joints and one standard centralizer every (3) joints to 2,500 ft. Run (1) Turbulent centralizer at 2,700 ft., 2,500 ft., 2,300ft., 2,000ft., 1,500 ft., and 1,000 ft. (NTL-FRA 90-1).
- 3. PRODUCTION CASING: 4-1/2" & 5-1/2" whirler type cement nose guide shoe with a latch collar on top of 20' bottom joint. Place marker joint above 5,400'. Place centralizers as needed across selected production intervals.

IV. CEMENTING:

(Note: Volumes may be adjusted onsite due to actual conditions)

- 1. <u>SURFACE</u>: Slurry: <u>150sx</u> (205 cu.ft.) of "Type III" + 2% CaCl₂ + ¼ # of cello-flake/sk (Yield = 1.39 cu.ft./sk, Weight = 14.5 #/gal.). The 100% excess should circulate cement to the surface. WOC 12 hours. Test csg to 1500psi.
- INTERMEDIATE: Lead 510 sx (1,063 cu.ft.) of "Type III" 65/35 poz with 8% gel, 1% CaCl₂ and 1/4# cello-flake/sk (Yield = 2.09 cu.ft./sk, Weight = 12.1 #/gal.). Tail 50 sx (70cu.ft.) of "Type III" with 1/4# cello-flake/sk, and 1% CaCl₂ (Yield = 1.4 cu.ft./sk, Weight = 14.5#/gal.). Use 100% excess in Lead Slurry to circulate to surface. No excess in Tail Slurry. Total volume = 1,133 cu.ft. Bump Plug to 1,500 psi. Notify engineering if cement is not circulated to surface.
- 3. PRODUCTION LINER: 10 bbl Gelled Water space. Lead: $50s\underline{x}$ (130ft³) of Premium Light HS + 1% FL-52 + .2% CD-32, 0.1% R-3, 3 #/sk CSE. (Yield = 2.59 cu.ft./sk, Weight = 11.6 #/gal.). Tail: $100 \underline{sx}$ (215 ft³) of Premium Light HS + 1% FL-52 + .2% CD-32, 0.1% R-3, 3 #/sk CSE, ¼ #/sk cello flake and 4% Phenoseal. (Yield = 2.15 ft³/sk, Weight = 12.3 #/gal.). Displace cement at a minimum of 8 BPM. The 20% excess in lead and tail should cover 100 ft into intermediate casing. Total volume 320 ft³. WOC 12 hours

V. IV COMPLETION

A. <u>CBL</u>

1. Run Cement Bond Log across all intervals to be perforated and find Top of Cement behind all casing strings if cement is not circulated to surface.

B. PRESSURE TEST

1. Pressure test 7" & 4-1/2" casing to 3300# for 15 minutes.

Williams Production

HALLIBURTON

Sperry Drilling Services




Project: Rio Arriba Co. NM NAD 83 Site: Sec. 34-T32N-R06W

> Well: Rosa Unit #129-C Wellbore: Wellbore #1

Plan: Plan 031906 (Rosa Unit #129-C/Wellbore #1)

CASING DETAILS							
TVD	MD	Name	Size				
3650.00	4002.91	7"	7				



Mancos Sh

Vertical Section at 344.00° (1000 ft/in)

Model: BGGM2005

+E/-W DLeg TFace MD TVD +N/-S Sec Inc Azi VSec Target 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 K.O.P. 0.00 400.00 400.00 0.00 0.00 0.00 0.00 0.00 0.00 End Build 1373.94 34.09 344.00 1317.49 270.38 -77.52 3.50 344.00 281.28 2639.39 34.09 344.00 2365.51 952.16 -272.97 Start Drop 0.00 0.00 990.51 0.00 3650.00 1330.69 -381.50 2.50 180.00 1384.30 7" Csg Pt RU #129C **End Drop** 4002.91 0.00 0.00 6050.00 1330.69 -381.50 6402.91 0.00 0.00 0.00 1384.30

SECTION DETAILS

WELLBORE TARGET DETAILS (MAP CO-ORDINATES)

Latittude


Date: 3/18/2006

Date:


Date:

Date:

Northing 2160922.43 Easting 2835468.56 Name +E/-W Shape 7" Csa Pt RU #129C 3650.00 1330.69 -381.50 Point



TD at 6402.91Approved:



Longitude

GENERAL ROSA DRILLING PLAN

Rosa Unit boundries:

T31N, R4W: all except sections 32-36 T31N, R5W: all except sections 1 & 2

T31N, R6W: all except sections 6,7,18,20, & 27-36

T32N, R6W: sections 32-36

FORMATION	LITHOLOGY	WATER	GAS	OIL/COND	OVER-PRES	LOST CIRC
Nacimiento	Interbedded shales, siltstones and sandstones	Possible	Possible	No	No	No
Ojo Alamo	Sandstone and conglomerates with lenses of shale	Fresh	No	No	No	No
Kirtland	Shale W/interbedded sandstones	No	Possible	No	No	No
Fruitland	Inter, SS, SiltSt, SH &Coals w/carb, SS, SiltSt, SH	Yes	Yes	No	Possible	Possible
Pictured Cliffs	Massive Sandstone w/thin interbedded shales	Possible	Yes	Possible	No	Possible
Lewis	Shale w/thin interbedded sandstones and siltstones	No	Possible	No	No	No
Cliff House	Transgressive sandstones	Possible	Yes	No	No	No
Menefee	Sandstones, carb shales and coal	Possible	Yes	No	No	No
Point Lookout	Regressive coastal barrier sandstone	Possible	Yes	Possible	No	Yes
Mancos	Marine shale and interbedded sandstone	No	Possible	Possible	No	Possible
Upr Dadota	Marine sand and shales	. No	Yes	Possible	No	Possible
Lwr Dakota	Fluvial sands, shales, & coal	Possible	Yes	Possible	No	Possible

DRILLING

Potential Hazards:

- 1. There are no overpressured zones expected in this well.
- 2. No H2S zones will be penetrated while drilling this well.

Mud System:

- Surface The surface hole will be drilled with a low-solids, non-dispersed system with starch and lost circulation material as needed. Expected mud weights will be in the 8.4 to 9.0 lb per gal range. Viscosities will be in the 30 to 60 sec/qrt range as needed to remove drill cuttings.
- 2. Intermediate The intermediate hole will be drilled with clear water and Benex to TD where the well will be mudded up to log and run casing. The mud system will be low-solids, non-dispersed with mud weights in the 9 to 10 lb per gal range as needed to control the well. Viscosities will be in the 45 to 55 range as needed to support any weight material. The weight material will consist of Barite.
- Production The well will be drilled using air from the intermediate casing point to TD. For Fruitland Coal wells, the coal section will be drilled with air/mist.

.v.mans rroduction Company, LLC

Well Control Equipment Schematic for 2M Service

Attachment to Drilling Technical Program

Typical BOP setup

