

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB No. 1004-0135  
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

Abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.

I-149-IND-8470

6. If Indian, Allottee or tribe Name

Allotted

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

GCU 320

9. API Well No.

30-045-24732

10. Field and Pool, or Exploratory Area

Pictured Cliffs

11. County or Parish, State

San Juan, New Mexico

UBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐

Oil Well

☒

Gas Well

☐

Other

2. Name of Operator

BP America Production Company Attn: Cherry Hlava

3a. Address

P.O. Box 3092 Houston, TX 77253

3b. Phone No. (include area code)

281-366-4081

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1850' FSL & 820' FEL Sec. 30 T28N, R12W NESE

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐

Notice of Intent

☒

Subsequent Report

☐

Final Abandonment Notice

TYPE OF ACTION

☒

Acidize

☐

Alter Casing

☐

Casing Repair

☐

Change Plans

☐

Convert to Injection

☐

Deepen

☐

Fracture Treat

☐

New Construction

☒

Plug and Abandon

☐

Plug Back

☐

Production (Start/Resume)

☐

Reclamation

☐

Recomplete

☐

Water Disposal

☐

Water shut-Off

☐

Well Integrity

☐

Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

8/11/06 TIH & set PKR @1296'. Load annulus w/13 bbls 2% KCL wtr. Rst CSG to 250 PSI. Held 5 min. Good Test.

8/15/06 Start Nitrogen downhole @5000 SCFM. Reached press of 980 PSI. Pmp'd 50,000 SCF then started methanol @5 BPM w/nitrogen reduced to 2250 SCFM. Pmp'd 2500 gallons methanol. Completed methanol pmping & switched back to pmping nitrogen @5000 SCFM. Again pmp'd 50,000 SCF. Shut Down. SI pres 525 PSI. Monitored well 1 hr. End of 1 hr Tubing pres @174 PSI.

8/16/06 TIH land tbg @1348'.

8/25/06 Well returned to production.

14. I hereby certify that the foregoing is true and correct  
Name (Printed/typed)

Cherry Hlava

Title Regulatory Analyst

Signature

Cherry Hlava

Date 09/07/06

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by

Title

Date

SEP 14 2006

Conditions of approval, if any, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOC