

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an  
Abandoned well. Use Form 3160-3 (APD) for such proposals.*

FORM APPROVED  
OMB No. 1004-0135  
Expires November 30, 2000

5. Lease Serial No.

**NMSF - 078040**

6. If Indian, Allottee or tribe Name

7. If Unit or CA/Agreement, Name and/or No.

**NMNM176063**

***SUBMIT IN TRIPLICATE - Other instructions on reverse side***

1. Type of Well



Oil Well



Gas Well



Other

8. Well Name and No.

**MUDGE GAS COM B IM**

2. Name of Operator

**BP AMERICA PRODUCTION COMPANY ATTN: Kristina Hurts**

9. API Well No.

**30-045-32735**

3a. Address

**PO BOX 3092 HOUSTON, TX 77253**

3b. Phone No. (include area code)

**281-366-3866**

10. Field and Pool, or Exploratory Area

**BASIN DAKOTA**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

**SESE 750FSL 745FEL**

11. County or Parish, State

**SAN JUAN, NM**

**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA**

**TYPE OF SUBMISSION**



Notice of Intent



Subsequent Report



Final Abandonment Notice

**TYPE OF ACTION**



Acidize



Deepen



Production (Start/Resume)



Water shut-Off



Alter Casing



Fracture Treat



Reclamation



Well Integrity



Casing Repair



New Construction



Recomplete



Other



Change Plans



Plug and Abandon



Water Disposal

Subsequent



Convert to Injection



Plug Back

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

10/09/06 MIRU. TIH SET CBP @ 5250'

11/04/06 TIH PERFORATED THE MESAVERDE FROM 4,816' TO 5,085' WITH 2 - JSPF.

11/17/06 PUMPED DOWN 4 1/2" CASING @ 60 BBLs. / MIN. USING 70 % QUILITY FOAM AND N2, USING SCHLUMBERGER CLEAR FRAC. USED 72,000 LBS. OF 16/30 BRADY SAND INTO THE FORMATION.

11/28/06 PRESSURE TEST BOP 2500# HIGH 250# LOW CHARTED O.K.

11/30/06 DRILL OUT CBP @ 5250'.


12/01/06 LANDED 2 3/8" TUBING @ 7017'.

14. I hereby certify that the foregoing is true and correct  
Name (Printed/typed)

**Kristina Hurts**

Title **Regulatory Analyst**

Signature



Date **12-04-06**

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**ACCEPTED FOR RECORD**

**DEC 05 2006**

**NMOCD**

**FARMINGTON FIELD OFFICE**