Form 3160-3 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB No. 1004-0136 Expires January 31, 2004

5. Lease Serial No.

_, NMSF-078769

BUREAU OF LAND MANA	AGEMENT	2 007 JA	8 71 6	., _, NMSF-078769	
APPLICATION FOR PERMIT TO D	RILL OR R		9 JI 1	6.4f Indian, Allottee or Tri	be Name
la. Type of Work: DRILL REENT	ER	2 10 %		7. If Unit or CA Agreement Rosa Unit NM 18. Lease Name and Well No.	1M-78407
1b. Type of Well: Oil Well Gas Well Other	⊠ s	ingle Zone 🔲 Multip	ole Zone	187C	
2. Name of Operator				9. API Well No.	
Williams Production Company 11 C				30-039-	30185
3a. Address	3b. Phone N	o. (include area code)		10. Field and Pool, or Explor	
P.O. Box 640 Aztec, NM 87410	(50 <u>5</u>)	634-4208		Blanco Mesaverde	
4. Location of Well (Report location clearly and in accordance with an	ny State requiren	ents. *)		11. Sec., T., R., M., or Blk. a	and Survey or Area
At surface 1090' FSL & 1145' FWL 🔥					
At proposed prod. zone 1650' FSL & 990' FWL	L			M Section 21, 31N, 5W	
14. Distance in miles and direction from nearest town or post office*				12. County or Parish	13. State
approximately 34 miles northeast of Blanco, New Mexico				Rio Arriba	NM
15. Distance from proposed* location to nearest property or lease line, ft.	16. No. of	Acres in lease	17. Spacin	g Unit dedicated to this well	
(Also to nearest drig. unit line, if any) 1090'		0.000		.0 (W/2)	
18. Distance from proposed location* to nearest well, drilling, completed, applied for, on this lease, ft.	19. Propos	•	1	BIA Bond No. on file	
21. Elevations (Show whether DF, KDB, RT, GL, etc.)	22 Approx	8' kimate date work will s		847 899 23. Estimated duration	
6.801' GR	1	1, 2007	uart	1 month	
0,001 GR		chments		- Tillonai	
The following, completed in accordance with the requirements of Onsl			ached to this	form:	
Well plat certified by a registered surveyor.	iole Oli aliu Qas			s unless covered by an existing	ng bond on file (see
2. A Drilling Plan.		Item 20 above). 5. Operator certific	ation		
 A Surface Use Plan (if the location is on National Forest Syster SUPO shall be filed with the appropriate Forest Service Office 		1 -	pecific info	rmation and/or plans as may	be required by the
25. Signature	Nam	e (Printed/Typed)		Date	
James Milyan		Larry Higgins		/	-31-0/
Title					
Drilling COM Approved by (Signature)	Nam	e (Printed/Typed)		Date	2/9/07
Title AFM	Offic	e ES			7110
Application approval does not warrant or certify that the applicant hole operations thereon. Conditions of approval, if any, are attached.	is legal or equite	able title to those rights in	n the subject	lease which would entitle the a	pplicant to conduct
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make States any false, fictitious or fraudulent statements or representations a			d willfully to	o make to any department or a	gency of the United
*(Instructions on reverse)				,	
Williams Exploration and Production Company, LLC, proposes the attached drilling and surface use plans.	to develop the	Blanco Mesaverde for	rmation at t	he above described location	in accordance with

The well pad surface is under jurisdiction of the BLM, Farmington Field Office.

This location has been archaeologically surveyed by La Plata Archaeological Consultants. Copies of their report have been submitted directly to the BLM and NMGF.

No access road is needed, as this is a twinned location. A pipeline tie of 115.4 feet would be required for this location. The pipeline would be located on Public lands. HOLD CIES FOR directional Survey

NOTIFY AZTEC OCD 24 hVS IN TIME TO WITNESS CS & CEMAN

District I PO Box 1980, Hobbs, NM 88241-1980

District II PO Drawer DD, Artesia, NM 88211-0719

District III 1000 Rio Brazos Rd., Aztec, NM 87410

District IV PO Box 2088, Santa Fe, NM 87504-2088

API Number

State of New Mexico Energy, Minerals & Natural Resources Department

Form C-102
Revised February 21, 1994
Instructions on back
Submit to Appropriate District Office
State Lease - 4 Copies
Fee Lease - 3 Copies

OIL CONSERVATION DIVISION

PO Box 2088 Santa Fe, NM 87504-2088 MM 7: 14

AMENDED REPORT


RECEPTED

WELL LOCATION AND ACREAGE DEDICATION PLAT

OIL CONS. DIV.


30-03	39-3	0185	5	72319	BLANCO MESAVERDE					
Property 1703			Property Name FWell Number ROSA UNIT 187C							
'0GRID N 12078			*Operator Name *Elevation WILLIAMS PRODUCTION COMPANY 6801							
					¹⁰ Surface	Location				
UL on lot no.	Section 21	Townshap 31N	Range 5W	Let Idn	Feet from the 1090	North/South line SOUTH	Feet from the	East/West line WEST	RIO ARRIBA	
		¹¹ B	ottom	Hole L	ocation I	f Different	From Surf	ace		
UL or lat no.	Section 21	Township 31N	Range 5W	Lat Idn	Feet from the 1650	North/South line SOUTH	Feet from the 990	Eest/West line WEST	County RIO ARRIBA	
Deducated Acres 320.0 Acres - (W/2)					¹⁹ Joint or Infill	³⁴ Consolidation Code	²⁵ Onder No.	·		

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



Office		ew Mexico	Form C-103
District I	Energy, Minerals an	d Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
District II	OIL CONSERVA	TION DIVISION	30-039-30185
1301 W. Grand Ave., Artesia, NM 88210 District III		st. Francis Dr.	5. Indicate Type of Lease FEDERAL X
1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE
District IV	Santa Fe,	NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			NMSF-078769
87505	C AND DEDODTE ON V	WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSAL	S AND REPORTS ON V		Rosa
DIFFERENT RESERVOIR. USE "APPLICAT			
PROPOSALS.)	<u></u>	,	8. Well Number
<u>`</u>	s Well 🛛 Other		187C
2. Name of Operator		}	9. OGRID Number
	duction Company, Ll	LC	120782
3. Address of Operator			10. Pool name or Wildcat
P.O. Bo	ox 640, Aztec, NM		Blanco Mesaverde
4. Well Location: Surface			
Unit Letter M : 1090	feet from the	line and 1115	feet from the W line
			· · · · · · · · · · · · · · · · ·
	<u> </u>		ounty Rio Arriba
	1. Elevation (Show whet	her DR, RKB, RT, GR, etc.)	
		6801' GR	
Pit or Below-grade Tank Application 🛛 or Cl			
Pit type_Drlg/Completion_Depth to Groun	dwater_>100 ft_Distance fr	om nearest fresh water well_>10	000 ft_ Distance from nearest surface water_>500 ft_
Pit Liner Thickness: 12 mil	Below-Grade Tank: Volu	ıme <u>bbls; Constru</u>	uction Material
12 Ch1- A		anto Nistano af Nistino I	Dan ant an Oth an Data
12. Check App	propriate box to mui	cate Nature of Notice, I	Report or Other Data
	NITION TO	SUBS	SEQUENT REPORT OF:
NOTICE OF INTE	-101111111111111111		
NOTICE OF INTE			
PERFORM REMEDIAL WORK [] F	PLUG AND ABANDON	REMEDIAL WORK	
PERFORM REMEDIAL WORK F	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRIL	ALTERING CASING LLING OPNS. PANDA
PERFORM REMEDIAL WORK F	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK	ALTERING CASING LLING OPNS. PANDA
PERFORM REMEDIAL WORK F TEMPORARILY ABANDON C PULL OR ALTER CASING M	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT	ALTERING CASING LLING OPNS. PANDA
PERFORM REMEDIAL WORK FTEMPORARILY ABANDON FOULL OR ALTER CASING FOULL OTHER:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER:	ALTERING CASING LLING OPNS. PAND A STORE
PERFORM REMEDIAL WORK FTEMPORARILY ABANDON FOR STANDARD	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly s	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and	ALTERING CASING LING OPNS. PAND A DOB DE LING
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON FOR TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly s	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and	ALTERING CASING LLING OPNS. PAND A STORE
PERFORM REMEDIAL WORK FTEMPORARILY ABANDON FOR STANDARD	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly s	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and	ALTERING CASING LING OPNS. PAND A DOB DE LING
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON FOR TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly s	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and	ALTERING CASING LING OPNS. PAND A DOB DE LING
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON CONTINUE CONT	CHANGE PLANS MULTIPLE COMPL Ed operations. (Clearly solution). SEE RULE 1103. For	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and Multiple Completions: Att	ALTERING CASING LING OPNS. PAND A DISTRIBUTION DE LING OPNS. PAND A DISTRI
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON CONTINUED TO THE PULL OR ALTER CASING NOTHER: 13. Describe proposed or complete of starting any proposed work) or recompletion. Drilling/Completion pit to be located	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ed operations. (Clearly s SEE RULE 1103. For	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and Multiple Completions: Att	ALTERING CASING LING OPNS. PAND A DISTRICT PAN
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON CONTINUE CONT	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ed operations. (Clearly s SEE RULE 1103. For approximately 50 to 7 ill be considered out of	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and Multiple Completions: Att feet from well head. Pit feet service once production	ALTERING CASING LING OPNS. PAND A DISTRICT PAN
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON COMPULL OR ALTER CASING NOTHER: 13. Describe proposed or complete of starting any proposed work) or recompletion. Drilling/Completion pit to be located additional site disturbance and pit w	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ed operations. (Clearly s SEE RULE 1103. For approximately 50 to 7 ill be considered out of	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and Multiple Completions: Att feet from well head. Pit feet service once production	ALTERING CASING LING OPNS. PAND A DISTRICT PAN
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON COMPULL OR ALTER CASING NOTHER: 13. Describe proposed or complete of starting any proposed work) or recompletion. Drilling/Completion pit to be located additional site disturbance and pit w	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ed operations. (Clearly s SEE RULE 1103. For approximately 50 to 7 ill be considered out of	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and Multiple Completions: Att feet from well head. Pit feet service once production	ALTERING CASING LING OPNS. PAND A DISTRICT PAN
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON COMPULL OR ALTER CASING NOTHER: 13. Describe proposed or complete of starting any proposed work) or recompletion. Drilling/Completion pit to be located additional site disturbance and pit w	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ed operations. (Clearly s SEE RULE 1103. For approximately 50 to 7 ill be considered out of	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and Multiple Completions: Att feet from well head. Pit feet service once production	ALTERING CASING LING OPNS. PAND A DISTRICT PAN
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON COMPULL OR ALTER CASING NOTHER: 13. Describe proposed or complete of starting any proposed work) or recompletion. Drilling/Completion pit to be located additional site disturbance and pit w	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ed operations. (Clearly s SEE RULE 1103. For approximately 50 to 7 ill be considered out of	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and Multiple Completions: Att feet from well head. Pit feet service once production	ALTERING CASING LING OPNS. PAND A DISTRICT PAN
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON CONTINUED TO TEMPORARILY ABA	CHANGE PLANS MULTIPLE COMPL Ed operations. (Clearly solution). SEE RULE 1103. For approximately 50 to 7 ill be considered out owith NMOCD guideline	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and Multiple Completions: Att f feet from well head. Pit f service once production es and Williams procedure	ALTERING CASING LING OPNS. PAND A DISTRICT PAN
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON FOR TEMPORARILY ABANDON	CHANGE PLANS MULTIPLE COMPL Ed operations. (Clearly statement). SEE RULE 1103. For approximately 50 to 7 ill be considered out owith NMOCD guideline over is true and complete.	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and Multiple Completions: Att feet from well head. Pit f service once production es and Williams procedure to the best of my knowledge	ALTERING CASING LING OPNS. PAND A DOB
PERFORM REMEDIAL WORK FEMPORARILY ABANDON CONTEMPORARILY ABANDON CONTEMPORA	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ed operations. (Clearly solution). SEE RULE 1103. For approximately 50 to 7 ill be considered out of with NMOCD guidelines over is true and complete sed according to NMOCD guidelines.	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and Multiple Completions: Att f feet from well head. Pit f service once production es and Williams procedure to the best of my knowledge idelines \(\times \), a general permit \(\times \)	ALTERING CASING LING OPNS. PAND A DISTRICT PAN
PERFORM REMEDIAL WORK FEMPORARILY ABANDON CONTEMPORARILY ABANDON CONTEMPORA	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ed operations. (Clearly solution). SEE RULE 1103. For approximately 50 to 7 ill be considered out of with NMOCD guidelines over is true and complete sed according to NMOCD guidelines.	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and Multiple Completions: Att f feet from well head. Pit f service once production es and Williams procedure to the best of my knowledge idelines \(\times \), a general permit \(\times \)	ALTERING CASING LING OPNS. PAND A DISTRICT PAN
PERFORM REMEDIAL WORK FEMPORARILY ABANDON CONTEMPORARILY ABANDON CONTEMPORA	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ed operations. (Clearly solution). SEE RULE 1103. For approximately 50 to 7 ill be considered out of with NMOCD guidelines over is true and complete sed according to NMOCD guidelines.	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and Multiple Completions: Att f feet from well head. Pit f service once production es and Williams procedure to the best of my knowledge idelines \(\times \), a general permit \(\times \)	ALTERING CASING LING OPNS. PAND A DOB
PERFORM REMEDIAL WORK FEMPORARILY ABANDON CONTEMPORARILY ABANDON CONTEMPORA	CHUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ed operations. (Clearly so the second se	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and Multiple Completions: Att f service once production as and Williams procedure to the best of my knowledge idelines , a general permit	ALTERING CASING LING OPNS. PAND A DISTRICT PAN
PERFORM REMEDIAL WORK FEMPORARILY ABANDON FEMPORA	CHUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ed operations. (Clearly so the second se	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and Multiple Completions: Att f service once production as and Williams procedure to the best of my knowledge idelines , a general permit	ALTERING CASING LING OPNS. PAND A DOB
PERFORM REMEDIAL WORK FEMPORARILY ABANDON FEMPORA	CHUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ed operations. (Clearly so the second se	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and Multiple Completions: Att f service once production as and Williams procedure to the best of my knowledge idelines , a general permit TLE TTLE TTLE	ALTERING CASING LING OPNS. PAND A DOB
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ed operations. (Clearly state of the complete of the considered out of the considered	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and Multiple Completions: Att feet from well head. Pit f service once production es and Williams procedure to the best of my knowledge idelines , a general permit TLE TTLE TTLE TY.higgins@williams.co	ALTERING CASING LING OPNS. PAND A DOWNS. PAND A DATE 1-31-07 DATE 1-31-07 DATE 1-31-07 DATE 1-31-07 DATE 1-31-07 DATE 1-31-07
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ed operations. (Clearly state of the complete of the considered out of the considered	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tate all pertinent details, and Multiple Completions: Att f service once production as and Williams procedure to the best of my knowledge idelines , a general permit	ALTERING CASING LING OPNS. PAND A DOWNS. PAND A DATE 1-31-07 DATE 1-31-07 DATE 1-31-07 DATE 1-31-07 DATE 1-31-07 DATE 1-31-07

WILLIAMS PRODUCTION COMPANY ROSA UNIT #187C 1090' FSL & 1145' FWL, SECTION 21, T31N, R5W, NMPM RIO ARRIBA COUNTY, NEW MEXICO ELEVATION: 6801'





WILLIAMS PRODUCTION COMPANY

Operations Plan

(Note: This procedure will be adjusted on site based upon actual conditions)

DATE:

1/16/2007

FIELD:

Blanco MV

WELL NAME:

Rosa #187C

Rio Arriba, NM

SURFACE:

FED

BH LOCATION:

NWSW Sec 21-31N-5W

MINERALS:

FED

SURF LOCATION:

SWSW Sec 21-31N-5W

ELEVATION:

6,801' GR

LEASE #

SF-078769

MEASURED DEPTH: 6,678

I. **GEOLOGY**:

Surface formation - San Jose

A. FORMATION TOPS: (KB)

Name	TVD	MD	Name	TVD	MD
Ojo Alamo	2,960	2,994	Cliff House	5,885	5,932
Kirtland	3,060	3,095	Menefee	5,930	5,977
Fruitland	3,485	3,527	Point Lookout	6,135	6,182
Pictured Cliffs	3,695	3,740	Mancos	6,445	6,492
Lewis	3,995	4,042	TD	6,630	6,678

- B. MUD LOGGING PROGRAM: none
- C. LOGGING PROGRAM: Cased Hole logs only
- **D.** <u>NATURAL GAUGES:</u> Gauge any noticeable increases in gas flow. Record all gauges in Tour book and on morning reports.

II. DRILLING:

- A. <u>MUD PROGRAM</u>: Clear water with benex to 7" casing point. Convert to a LSND mud to log and run pipe. Treat for lost circulation as necessary. Obtain 100% returns prior to cementing. Notify Engineering of any mud losses. Use air w/Air Hammer from 7 in, csg.to TD.
- B. <u>BOP TESTING</u>: While drill pipe is in use, the pipe rams and the blind rams will be function tested once each trip. The anticipated reservoir is expected to be less than 1300 psi, so the BOPE will be tested to 250 psi (Low) for 5 minutes and 1500 psi (High) for 10 minutes. Utilize a BOPE Testing Unit with a recording chart and appropriate test plug for testing. The drum brakes will be inspected and tested each tour. All tests and inspections will be recorded in the tour book as to time and results.

III. MATERIALS

A. CASING PROGRAM:

CASING TYPE	OH SIZE (IN)	DEPTH (MD) (FT)	CASING SIZE (IN)	WEIGHT(LB) GRADE
Surface	12 1/4	300	9 5/8	36 K-55
Intermediate	8 3/4	4,217	7	20 K-55
Liner	6 1/4	4,117 6,678	4 1/2	10.5 J-55

B. FLOAT EQUIPMENT:

- 1. <u>SURFACE CASING:</u> 9-5/8" notched regular pattern guide shoe. Run (1) standard centralizer on each of the bottom (3) joints of Surface Casing.
- 2. <u>INTERMEDIATE CASING:</u> 7" cement nose guide shoe with a self-fill insert float. Place float collar one joint above the shoe. Install (1) Turbulent centralizer on each of the bottom (3) joints and one standard centralizer every (3) joints to 2,500 ft. Run (1) Turbulent centralizer at 2,700 ft., 2,500 ft., 2,300ft., 2,000ft., 1,500 ft., and 1,000 ft. (NTL-FRA 90-1).
- 3. <u>PRODUCTION CASING:</u> 4-1/2" whirler type cement nose guide shoe with a latch collar on top of 20' bottom joint. Place marker joint above 5,400'. Place centralizers as needed across selected production intervals.

IV. CEMENTING:

(Note: Volumes may be adjusted onsite due to actual conditions)

- 1. <u>SURFACE</u>: Slurry: <u>150sx</u> (205 cu.ft.) of "Type III" + 2% CaCl₂ + ½ # of cello-flake/sk (Yield = 1.39 cu.ft./sk, Weight = 14.5 #/gal.). The 100% excess should circulate cement to the surface. WOC 12 hours. Test csg to 1500psi.
- 2. <u>INTERMEDIATE:</u> Lead <u>540 sx</u> (1128) cu.ft.) of "Premium Light" with 8% gel, 1% CaCl₂ and 1/4# cello-flake/sk (Yield = 2.09 cu.ft./sk, Weight = 12.1 #/gal.). Tail 50 <u>sx</u> (70cu.ft.) of "Type III" with 1/4# cello-flake/sk (Yield = 1.4 cu.ft./sk, Weight = 14.5#/gal.). Use **100%** excess in Lead Slurry to circulate to surface. No excess in Tail Slurry. Total volume = 1,198 cu.ft. Bump Plug to 1,500 psi. Notify engineering if cement is not circulated to surface.
- 3. PRODUCTION LINER: 10 bbl Gelled Water spacer. Cement: 155 sx (328 ft³) of Premium Light HS + 1% FL-52 + .2% CD-32, 0.1% R-3, 3 #/sk CSE, ¼ #/sk cello flake and 4% Phenoseal. (Yield = 2.15 ft³/sk, Weight = 12.3 #/gal.). Displace cement at a minimum of 8 BPM. The 20% excess in lead and tail should cover 100 ft into intermediate casing. Total volume 328 ft³. WOC 12 hours

V. IV COMPLETION

A. CBL

1. Run Cement Bond Log across all intervals to be perforated and find Top of Cement behind all casing strings if cement is not circulated to surface.

Rosa #187C Dir Ops Plan

B. PRESSURE TEST

1. Pressure test 7" & 4-1/2" casing to max 3000 psi, hold at 1500 psi for 30 minutes.

C. STIMULATION

- 1. Perforate the Point Lookout as determined from the open hole logs.
- 2. Stimulate with approximately 9,300# of 14/30 LitePropTM sand in slick water.
- 3. Isolate Point Lookout with a CIBP.
- 4. Perforate the Menefee/Cliff House as determined from the open hole logs.
- 5. Stimulate with approximately 9,300# of 14/30 LiteProp[™] sand in slick water.
- 6. Test each zone before removing bridge plugs.

D. RUNNING TUBING

1. <u>Mesa Verde:</u> Run 2-3/8", 4.7#, J-55, EUE tubing with a SN (1.91" ID) on top of bottom joint. Land tubing approximately 25' above the bottom Point Lookout perforation.

Gary Sizemore

Sr. Drilling Engineer

Rosa #187C Dir Ops Plan.doc





Weatherford

Rosa Unit 187 C Section 21 T 31N R 5W 1090' FSL & 1145' FWL Rio Arrba County, NM Plan 1

Frue Vertical Depth [1000ft/in]

6000

7000

6500 1 66

	SECTION DETAILS										
Sec	MD	Inc	Azi	TVD	+N/-S	+E/-W	DLeg	TFace	VSec	Target	
1	0.00	0.00	344.02	0.00	0.00	0.00	0.00	0.00	0.00		
2	400.00	0.00	344.02	400.00	0.00	0.00	0.00	0.00	0.00		
3	725.00	9.75	344.02	723,43	26.52	-7.59	3.00	344.02	27.59		
4	3758.79	9.75	344.02	3713.40	520.44	-149.04	0.00	0.00	541.36		
5	4217.60	0.00	344.02	4170.00	557.88	-159.76	2.13	180.00	580.30	Int. Cs. Pt	
6	6677.60	0.00	344.02	6630.00	557.88	-159.76	0.00	344.02	580.30	PBHL	


KB ELEVATION: 6815' GR ELEVATION: 6801'

WELL DETAILS								
Name	+N/-S	+E/-W	Northing	Easting	Latitude	Longitude	Slot	
Rosa Unit 187 C	0.00	0.00	2140269.14	2857795.65	36°52'50.916N	107°22'21.972W	N/A	



	TARGET DETAILS										
Name	TVD	+N/-S	+E/-W	Latitude	Longitude	Shape					
Int. Cs. Pt. PBHL	4170.00 6630.00	557.88 557.88	-159.76 -159.76	36°52'56.432N 36°52'56.432N	107°22'23.938W 107°22'23.938W	Point Circle (Radius: 50)					

700




0° 6678 MD TD

1000

500

Vertical Section at 344.02° [1000ft/in]



FORMATION TOP DETAILS								
No.	TVDPath	MDPath	Formation					
1	2960.00	2994.34	Oio Alamo					
2	3060.00	3095.81	Kirtland					
3	3485.00	3527.04	Fruitland					
4	3695.00	3740.12	Pictured Cliffs					
5	3995.00	4042.47	Lewis					
6	5570.00	5617.60	Cliff House Trans					
7	5885.00	5932.60	Cliff House					
8	5930.00	5977.60	Menefee					
9	6135.00	6182.60	Point Lookout					
10	6445.00	6492.60	Mancos					

Plan: Plan #1 (Rosa Unit 187 C) Created By: Jose Perez Dat Weatherford Drilling Services 11943 FM 529 Houston TX USA 77041 (713) 896 8194 MAIN (713) 896 0498 FAX Date: 01/15/06

GEOLOGIC PROGNOSIS

Company:

Williams Production Company. LLC

Project:

2007 Drilling Plan

Area:

Rosa Unit

Operator: Well Name:

Williams Production Company. LLC Rosa Unit No. 187C (Kmv-Directional)

Location: Footage: County/State: SWSW 21-31N-05W 1090' FSL & 1145' FWL

Rio Arriba/New Mexico

Surveyed GL:

6801

Estimate (14') KB:

6815

Formation Programme 1	Thickness	<u>TVD</u>	Struct. Elev.
San Jose Fm.	2960	Surface	6801
Ojo Alamo Ss.	100	2960	3855
Kirtland Sh.	425	3060	3755
Fruitland Fm.	210	3485	3330
Pictured Cliffs Ss.	300	3695	3120
Lewis Sh.	175	3995	2820
Intermediate Casing Depth	1400	<u>4170</u>	2645
Cliff House Ss. Trans.	315	5570	1245
Cliff House Ss.	45	5885	930
Menefee Fm.	205	5930	885
Point Lookout Ss.	310	6135	680
Mancos Sh.	185	6445	370
Total Depth	NA	<u>6630</u>	185

Mechanical Logs:

Cased hole (TMDL, CBL) logs only

Correlation Logs:

Rosa Unit No. 111 (SESW 21-31N-05W)


Notes:

This well will be directionally drilled to a BHL 1650' FSL & 0990' FWL 21-31N-05W

Well Control Equipment Schematic for 2M Service

Attachment to Drilling Technical Program

Exhibit #1 Typical BOP setup



GENERAL ROSA DRILLING PLAN

Rosa Unit boundries:

T31N, R4W: all except sections 32-36 T31N, R5W: all except sections 1 & 2

T31N, R6W: all except sections 6,7,18,20, & 27-36

T32N, R6W: sections 32-36

FORMATION	LITHOLOGY	WATER	GAS	OIL/COND	OVER-PRES	LOST CIRC
Nacimiento	Interbedded shales, siltstones and sandstones	Possible	Possible	No	No	No
Ojo Alamo	Sandstone and conglomerates with lenses of shale	Fresh	No	No	No	No
Kirtland	Shale W/Interbedded sandstones	No	Possible	No	No	Nσ
Fruitland	Inter, SS, SiltSt, SH &Coals w/carb, SS, SiltSt, SH	Yes	Yes	No	Possible	Possible
	Massive Sandstone w/thin interbedded shales	Possible	Yes	Possible	No	Possible
	Shale within interbedded sandstones and siltstones	No	Possible	No	No	No
Cliff House	Transgressive sandstones	Possible	Yes	No	No	No
Menefee	Sandstones, carb shales and coal	Possible	Yes	No	No	No
Point	Regressive coastal barrier	Possible	Yes	Possible	No	Yes
Lookout	sandstone					
Mancos	Marine shale and interbedded sandstone	No	Possible	Possible	No	Possible
Jpr Dadota	Marine sand and shales	No	Yes	Possible	No	Possible
wr Dakota	Fluvial sands, shales, & coal	Possible	Yes	Possible	No	Possible

DRILLING

Potential Hazards:

- 1. There are no overpressured zones expected in this well.
- 2. No H2S zones will be penetrated while drilling this well.

Mud System:

- Surface The surface hole will be drilled with a low-solids, non-dispersed system with starch and lost circulation material as needed. Expected mud weights will be in the 8.4 to 9.0 lb per gal range. Viscosities will be in the 30 to 60 sec/qrt range as needed to remove drill cuttings.
- 2. Intermediate The intermediate hole will be drilled with clear water and Benex to TD where the well will be mudded up to log and run casing. The mud system will be low-solids, non-dispersed with mud weights in the 9 to 10 lb per gal range as needed to control the well. Viscosities will be in the 45 to 55 range as needed to support any weight material. The weight material will consist of Barite.
- Production The well will be drilled using air from the intermediate casing point to TD. For Fruitland Coal wells, the coal section will be drilled with air/mist.