## 5. Lease UNITED STATES NMNM-03547 DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT** 6. If Indian, Affortee of Tribe Name 7. Unit Agreement Name RECEIVED SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different BLM reservoir. Use "APPLICATION FOR PERMIT--" for such proposals) 8. Well Name and Not All 11. 131 111 1. Oil Well [ ] Gas Well [ ] Other [ ] **GAS WELL** BREECH "F" 16 9. API Well No. 2. Name of Operator: 30-039-29998-00S1 Caulkins Oil Company 3. Address of Operator: 10. Field and Pool, Exploratory Area (505) 334-4323 1409 W. Aztec Blvd. Ste B7, Aztec, NM 87410 **BASIN DAKOTA** 4. Location of Well (Footage, Sec., Twp., Rge.) 11. Country or Parish, State SEC. 33-27N-6W 1900' F/N 890' F/W Rio Arriba Co., New Mexico 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION [ ] Notice of Intent [ ] Abandonment [ ] Change of Plans [ ]Recompletion [ ] New Construction [X] Subsequent Report [ ] Plugging Back [ ] Non-Routine Fracturing [ ] Casing Repair [ ] Water Shut-Off [ ] Altering Casing [ ] Conversion to Injection [ ] Final Abandonment Notice [X] Other Well Completion 1 Dispose Water 17. Describe Proposed or Completed Operations: 4-12-07 Rigged up. RCVD MAY25'07 T. I. H. with 4 3/4" bit on 2 3/8" tubing. To OIL CONS. DIV. 4-19-07 Drilled out stage tool at 3705'. DIST. 3 Drilled out stage tool at 5737'. Cleaned out to 7707'. Rolled hole with 2% KCL water. Pressure tested casing to 4000#, held OK. T. O. H. with 2 3/8" tubing. Ran GSL and CBL logs. Top of cement at 5446'. Perforated Dakota zone with 40 select fire holes, 7603' to 7378'. Frac'd well with 170,690# 20/40 sand and 2,250,000 scfm N<sub>2</sub> foam. Flowed well back, (continued on page 2) NOTE: The format is issued in lieu of U.S. BLM Form 3160-5 18. I HEREBY CERTIFY THE FOREGOING IS TRUE AND CORRECT SIGNED: Hert 2 Years TITLE: Superintendent DATE: May 22, 2007

SIGNED: Note: Note: Note: Note: May 22, 2007

ROBERT L. VERQUER

TITLE: Superintendent DATE: May 22, 2007

APPROVED BY: DATE: DATE: ACCEPTED FOR RECORD

CONDITIONS OF APPROVAL, IF ANY

MAY 2 4 2007

Caulkins Oil Company BLM Sundry Notice Breech "F" 16 May 22, 2007 Page 2

T. I. H. with new 2 3/8" production tubing.

Cleaned out to 7704' with air package.

Landed tubing on doughnut at 7572'.

Rigged down and moved.

Well waiting on tie-in.

NOTE: No cement behind pipe, 5446' to 3734'.

We intend to cement this area behind pipe, but request approval to wait until South Blanco Tocito zone in this well has been perforated so that we can frac Tocito zone down casing. Immediately following Tocito completion, Caulkins will cement 5446' to 3734'.