

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
*Do not use this form for proposals to drill or to re-enter an
Abandoned well. Use Form 3160-3 (APD) for such proposals.*

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

5. Lease Serial No.

JIC CONTRACT 148

6. If Indian, Allottee or tribe Name

JIC APACHE

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE – Other instructions on reverse side

i. ☐ Oil Well ☒ Type of Well Gas Well ☐ Other

8. Well Name and No.

JIC APACHE 148 37

2. Name of Operator
BP AMERICA PRODUCTION COMPANY

9. API Well No.

30-039-23786

3a. Address
P.O. BOX 3092 HOUSTON, TX 77253

3b. Phone No. (include area code)
281-366-4081

10. Field and Pool, or Exploratory Area
W. LINDRITH GALLUP-DAKOTA

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Sec. 13 T25N R05W NENW 990' FNL & 1660' FWL

11. County or Parish, State
RIO ARRIBA, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Deepen

☐ Production (Start/Resume)

☐ Water shut-Off

☐ Alter Casing

☐ Fracture Treat

☐ Reclamation

☐ Well Integrity

☐ Casing Repair

☐ New Construction

☐ Recomplete

☐ Other

☐ Change Plans

☐ Plug and Abandon

☐ Water Disposal

Perf Same Sand

☐ Convert to Injection

☐ Plug Back

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

SEE ATTACHMENT

14. I hereby certify that the foregoing is true and correct
Name (Printed/typed)

CHERRY HLAVA

Title **REGULATORY ANALYST**

Signature

Cherry Hlava

Date **8/12/03**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

/s/ David R. Sitzler

Division of Multi-Resources

Date

SEP 18 2003

Conditions of approval, if any, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

JICARILLA CONTRACT 148 37
PERFS ADDED TO SAME RESERVOIR
8/12/03

7/18/03 SPOT EQUIP. SDF WEEKEND.

7/21/03 SPOT & LEVEL RIG, RU EQUIP. LAY 3" LINES TO BLW BACK TNK, TBG 9, CSG 0 PSI. BH 0 PSI. NDWH & NU BOPs. TOH w/TBG. SDON.

7/22/03 TIH w/MILL, TAG CIBP @6950'. RU PWR SWIVEL, BREAK CIRC w/AIR MIST. MILL ON PLUG, RD SWVL. TIH w/TBG; TAG @8010'. PULL ABOVE PERFS SDFN.

7/23/03 CSG 840 PSI, TBG 0 PSI, TIH & MILL ON CIBP @ 8010'. PUSH TO PBTD @ 8150'. SDON.

7/24/03 CSG 840 PSI, TIH w/3.125 GUN & PERF DAKOTA 6998' - 7360' @ 2 JSPF. PERF 7836' - 8022' @ 4 JSPF. TOTAL OF 988 SHOTS.

7/25/03 CSG 550 PSI, SD for Weekend.

7/28/03 CSG 950 PSI. TIH w/scraper to 8150'. Circ out 22 bbls wtr. Blw for 2 hrs. Making 13 - 15 BPH of wtr. RD Let fow natural, 2 PSI on 2" line. SDON.

7/29/03 CSG 840 PSI, BWD, TIH TO 8150'. RU SWIVEL BREAK CIRC w/AIR MIST, UNLOAD 35 bbls of WTR. RD SWIVEL. TOH w/TBG. TIH w/BHA. LAND TBG @7564'. TEST TBG TO 500 PSI w/AIR, HELD 5 MIN. GOOD TEST. NDBOP's, NUWH. RD EQUIPMENT. SDON.

7/30/03 RD UNIT. CLEAN LOCATION. RELEASE UNIT.