

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
*Do not use this form for proposals to drill or to re-enter an
Abandoned well Use Form 3160-3 (APD) for such proposals.*

FORM APPROVED
OMB No 1004-0135
Expires November 30, 2000

5 Lease Serial No

SF - 078499

2076 AUG 16 AM 11:25
Indian, Allottee or tribe Name

7 If Unit or CA/Agreement, Name and/or No

8 Well Name and No
Russell LS 4A

9 API Well No

30-045-23702

10 Field and Pool, or Exploratory Area

Otero Chacra & Blanco Mesaverde

11 County or Parish, State

San Juan County, New Mexico

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1 Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2 Name of Operator

BP America Production Company Attn: Cherry Hlava

3a Address

P.O. Box 3092 Houston, TX 77253

3b Phone No (include area code)

281-366-4081

4 Location of Well (Footage, Sec., T, R, M, or Survey Description)

1630' FNL & 900' FWL SEC 24 T28N R08W

12 CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Deepen

☐ Production (Start/Resume)

☐ Water shut-Off

☐ Alter Casing

☐ Fracture Treat

☐ Reclamation

☐ Well Integrity

☐ Casing Repair

☐ New Construction

☒ Recomplete

☒ Other DHC 2586AZ
Aprv'd 5/1/07

☐ Change Plans

☐ Plug and Abandon

☐ Water Disposal

☐ Convert to Injection

☐ Plug Back

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection

RCVD AUG 23 '07

8/6/07 CSG 500#, TBG 0# BH 0#. Blow DN to flare pit. Pres test BOPs to 250# low & 1500# high ok.

OIL CONS. DIV.

8/9/07 TIH; clean out to Bridge plug @ 4450'.

8/10/07 Blow DN to flare pit; drill out Bridge Plug @ 4450'. Clean out to PBTD @ 5506'.

DIST. 3

8/13/07 Pres test BOP to 200# low & 1500# high; good test.

8/14/07 TIH land 2 3/8", 4.7#, J-55 TBG @ 5412'. Rig down move off location. Turn well over to production.

- 14 I hereby certify that the foregoing is true and correct
Name (Printed/typed)

Cherry Hlava

Title Regulatory Analyst

Signature

Cherry Hlava

Date 08/15/2007

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached Approval of this notice does not warrant or
Certify that the applicant holds legal or equitable title to those rights in the
subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States
any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

ACCEPTED FOR RECORD

AUG 21 2007

NMOCD

FARMINGTON FIELD OFFICE

8