



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401



IN REPLY REFER TO
SF-078502 et al. (WC)
3162.3-1.0 (019)

FEB. 7 1992

Amoco Production Company
P.O. Box 800
Denver, CO 80201

RECEIVED
FEB 10 1992
OIL CON. DIV. 1
DIST. 3

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos.:

1. 12 Vandewart "A". Section 11, T. 29 N., R. 8 W., San Juan County, New Mexico, lease SF-078502.
2. 63 Mudge "B". Section 21, T. 31 N., R. 11 W., San Juan County, New Mexico, lease SF-078096.

As discussed with Cindy Burton of your company on January 28, 1992, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

John L. Keller
Chief, Branch of Mineral Resources

2 Enclosures

cc:

New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

ABANDONED LOCATION