

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to open or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

OIL WELL GAS WELL OTHER

1. NAME OF OPERATOR
Aztec Oil and Gas Company

2. ADDRESS OF OPERATOR
Drawer 570, Farmington, New Mexico

3. LOCATION OF WELL (Report location clearly and in accordance with State requirements. See also space 17 below.)
At surface
810 FSL & 870 TEL, Sec. 15-28N-13W

4. PERMIT NO. _____

5. ELEVATIONS (Show whether DF, RT, CR, etc.)
6078 Gr

6. LEASE DESIGNATION AND SERIAL NO.
NM 09979

7. THE INDIAN, ALLOTTEE, OR TRIBE NAME

8. UNIT AGREEMENT NAME

9. FARM OR LEASE NAME
Robinson

10. WELL NO.

11. FIELD AND POOL, OR WILDCAT
Basin Dakota

12. SEC., T., R., M., OR BLM. AND SURVEY OR AREA
Sec. 15-28N-13W

13. COUNTY OR PARISH
San Juan

14. STATE
New Mexico

OIL CON. COM. DIST. 3
NOV 13 1968

OK *W*

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO			SUBSEQUENT REPORT OF		
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>		
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>		
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT <input type="checkbox"/>		
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) _____	Installing pump <input checked="" type="checkbox"/>		

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Moved unit on location. Pulled 2" tubing. Ran 197 joints 2" with mud anchor, perforated nipple, and seating nipple landed 6282'. Packed off well.

RECEIVED
NOV 13 1968
OIL CON. COM.
DIST. 3

RECEIVED
NOV 12 1968
U.S. GEOLOGICAL SURVEY
FARMINGTON, N.M.

18. I hereby certify that the foregoing is true and correct

SIGNED *John A. [Signature]* TITLE District Superintendent DATE 11-11-68

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY _____