UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANGEMENT

RECEIVE

FORM APPROVED OMB No 1004-0135 Expires July 31, 2010

MAY 0 5 20085

Lease Senal No

SUNDRY NOTICES AND REPORTS ON WEI	•	•

SF 079244-A Do not use this form for proposals to drill or to re-entguireau of Land Management Abandoned well Use Form 3160-3 (APD) for such proposalisamington Field Coffice If Indian. Allottee or tribe Name If Unit or CA/Agreement Name and/or No SUBMIT IN TRIPLICATE – Other instructions on reverse side Type of Well Well Name and No Other Oil Well Gas Well Gallegos Canyon Unit 36 Name of Operator API Well No BP America Production Company Attn. Cherry Hlava 30-045-07330 Address 3b Phone No (include area code) Field and Pool, or Exploratory Area P.O. Box 3092 Houston, TX 77253 281-366-4081 Fruitland Coal Location of Well (Footage, Sec., T, R, M, or Survey Description) County or Parish, State 1758' FNL & 1013' FEL SEC 19 T28N R12W San Juan County, New Mexico 12 CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE. REPORT. OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Deepen Deepen Production (Start/Resume) Acidize Water shut-Off Notice of Intent Reclamation Alter Casing Fracture Treat Well Integrity Other Acid Job Casing Repair New Construction Recomplete Subsequent Report Change Plans Plug and Abandon Water Disposal Plug Back Final Abandonment Notice Convert to Injection Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof 13 If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection 4/18/08 TIH TAG AT 1416', TIH SET PKR @ 1377', LOAD CASING WITH 45 bbls PRODUCED WATER PRESSURE TEST TO 500 PSI, HELD 5 MIN. GOOD TEST. RELEASE PACKER. 4/22/08 TIH pmp 6000 gal nitrified acid down casing Pressure came up to 1890 psi, broke back to 600. H2S monitors went off, 47 PPM H2S, shut well in Most likely reaction from scale being in the annulus & acid dissolving it. Leave CSG open & monitoring the wind. Open csg to flw back tank @ 0 psi RCUD MAY 13'08 4/23/08 Rig Down move off location. Will come back later & finish job I hereby certify that the foregoing is true and correct OIL CONS. DIV. Name (Printed/typed) Cherry Hlava Regulatory Analyst 04/30/2008 Signature Cherry Hlava Date

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter witin its jurisdiction


THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Title

Office

Date

MAY 1 2 2008





Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or

Certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon