

New Mexico Energy, Minerals and Natural Resources Department

Bill Richardson
Governor

Joanna Prukop
Cabinet Secretary
Reese Fullerton
Deputy Cabinet Secretary

Mark Fesmire
Division Director
Oil Conservation Division



October 7, 2008

Sharon Zubrod
Burlington Resources Oil and Gas Company
PO Box 4289
Farmington NM 87499

Re: Newberry 12-N, B, 4, 31N, 12W, API # 30-045-33060

Dear Ms. Zubrod:

The 2008 Bradenhead test on the above well indicates a failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before January 9, 2009. Initial intermediate psi of 641 was reported with a 5 minute shut in pressure of 1 psi. Bradenhead pressure was 0 psi.

With your sundry please attach a copy of the last two tests, a current wellbore schematic including formation and cement tops. Indicate the method used to determine the cement tops, and provide gas analysis from all casing strings.

Reference: RBDMS KGR0828164025 on future correspondence.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Kelly G. Roberts
Deputy Oil and Gas Inspector
District III-Aztec

CC: Well File

