Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135

Expires: March 31, 1993 5. Lease Designation and Serial No

NM-081208 (12335) SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE 1. Type of Well Oil Well 8. Well Name and No. Other Injection 2. Name of Operator So. Hospah Unit #5 9. API Well No. Citation Oil & Gas Corp. 3. Address and Telephone No. 10. Field and Pool, or Exploratory Area 8223 Willow Place South Ste 250 Houston, TX 77070 713-469-9664 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) South Hospah Upper Sand 11. County or Parish, State Unit B 990' FNL & 2712' FEL Sec.12, T17N, R9W McKinley County, NM CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12. TYPE OF ACTION TYPE OF SUBMISSION Notice of Intent Change of Plans Abandonment Recompletion **New Construction** Subsequent Report Plugging Back Non-Routine Fracturing Water Shut-Off Casing Repair Final Abandonment Notice Conversion to Injection Altering Casing Othe Conversion to producer Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Citation Oil & Gas Corp. proposes to convert the South Hospah Unit #5 well from an injector to a producer in the Lower Hospah Sand. Swab well in to bleed pressure off. MIRU. NU BOP. TOOH, LD tbg. Redress pkr. TIH w/tbg collar, redressed Lok-set pkr, SN and 2 3/8" tbg to ±1600'.

Circulate pkr fluid. ND BOP. Set pkr w/±8K tension. NU WH.

Perforate Lower Hospah 1614' - 1619' inclusive w/4 spf. RD WL

Swab test. Acidize if necessary. Swab back acid. Run pump & rods.

Tie injection line into production system. Produce. - Pressure fest casing & repair

		& COA.	
14. I hereby certify that the foregoing is true and correct Signed Shown Wand	Title Prod. Reg. S	DIST. 2 DIV.	93
(This space for Federal or State office use)		AS AME	NDED
Approved by	Title	Date	1993

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United states or representations as to any matter within its jurisdiction.