

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 9741
7. Unit Agreement Name
8. Form or Lease Name Bolack Santa Fe
9. Well No. #9
10. Field and Pool, or Wildcat Wildcat
12. County McKinley

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	7. Unit Agreement Name
2. Name of Operator Tom Bolack	8. Form or Lease Name Bolack Santa Fe
3. Address of Operator 1010 N. Dustin Ave. Farmington N. Mexico	9. Well No. #9
4. Location of Well UNIT LETTER K 1650 FEET FROM THE South 1650 FEET FROM THE West 9 LINE, SECTION 18N TOWNSHIP 6 W RANGE 6 W NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 7352 G.L.	12. County McKinley

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-23-65 T.D. 3488 P&A

Abandoned well in the following manner:

Set Plug 3300-3488 w/30 Sax 6 1/8" hole
Set Plug 2150-2250 w/30 Sax 7 7/8" hole
Set Plug 345-445 w/30 Sax 7 7/8" hole
Set 10 Sax @ surface
Installed Abandonment Marker



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *P. F. Stone* TITLE President Stone Drilling Inc. DATE 10-25-65
APPROVED BY *Ed R. Kendrick* TITLE PETROLEUM ENGINEER DIST. NO. 3 DATE 8-3-66
CONDITIONS OF APPROVAL, IF ANY: