

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
*****	
7. Unit Agreement Name	
*****	
8. Farm or Lease Name	
Santa Fe "B"	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Hospah-Gallup	
12. County	
McKinley	

<p align="center"><b>SUNDRY NOTICES AND REPORTS ON WELLS</b></p> <p align="center">(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>	
<p>1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dry Hole</b></p>	
<p>2. Name of Operator</p> <p><b>Shelly Oil Company</b></p>	
<p>3. Address of Operator</p> <p><b>P. O. Box 730 - Hobbs, New Mexico</b></p>	
<p>4. Location of Well</p> <p>UNIT LETTER <b>"P"</b> <b>640</b> FEET FROM THE <b>South</b> LINE AND <b>835</b> FEET FROM</p> <p>THE <b>East</b> LINE, SECTION <b>6</b> TOWNSHIP <b>17-N</b> RANGE <b>9-W</b> N.M.P.M.</p>	
<p>15. Elevation (Show whether DF, RT, GR, etc.)</p> <p><b>6613' GR</b></p>	

<p>16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>	
<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>SUBSEQUENT REPORT OF:</p> <p>REMEDIAL WORK <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p> <p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input checked="" type="checkbox"/></p>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well plugged and abandoned in the following manner:

1. Spotted 30-sack cement plug from 1600-1459' (Hospah).
2. Spotted 30-sack cement plug from 436-295' (Point Lookout).
3. Spotted 10-sack cement cap in top of 7" casing and installed 4" pipe as dry hole marker.
4. All intervals not cemented were filled with heavy mud laden fluid.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED (ORIGINAL SIGNED) H. E. Aab TITLE District Superintendent DATE July 12, 1966

APPROVED BY A. R. Kendrick PETROLEUM ENGINEER DIST. NO. 3 DATE 7-27-66

CONDITIONS OF APPROVAL, IF ANY: