

OIL CONSERVATION COMMISSION
1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

June 1, 1966

Harold H. Brown
Petroleum Club Plaza
Farmington, New Mexico

Dear Mr. Brown:

We have received Well Record Form C-105 for the E.B. Clark Santa Fe Pacific #1 well located in Unit D, Section 35-17N-9W.

You state in the accompanying letter that the well has been plugged back to 370 feet and remains a water well for the landowner. Form C-103 should be filed in triplicate as a notice of intention to plug showing exactly where cement plugs were to be set and 3 copies of Form C-103 as a subsequent plugging report showing where plugs were placed. I assume from your letter that you have already mailed the landowner copies of the Affidavit to Convert to Water Well, so that he may assume responsibility for the well.

If you have any further questions, please contact us.

Yours very truly

Emery C. Arnold
Supervisor, Dist. #3

ECA: ks

Encis.

OIL CONSERVATION COMMISSION
1000 RIO BRAZOS BLVD
AUSTIN, TEXAS 78701

June 1, 1966

Mr. J. L. Brown
Petroleum Development
San Antonio, Texas

Dear Mr. Brown:

We have received your letter dated June 1, 1966, for the O.C. Form 0-103 for the well located in Unit 1, Section 36, T24N, R10E, S10E.

You state in the accompanying letter that the well has been plugged back to 370 feet and remains a water well for the remainder of the life of the well. Form 0-103 should be filed in triplicate as a condition of intention to plug showing exactly where cement plugs were to be set and 2 copies of Form 0-103 as a subsequent plug or report showing where plugs were placed. I assume from your letter that you have already mailed the landowner copies of the Affidavit to Convert to Water Well, so that we may assume responsibility for the well.

If you have any further questions, please contact us.

Very truly yours,

John A. Smith
Superintendent, Division of

cc: Mr. Brown

cc: Mr. Smith