

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Chaco Oil Company	8. Farm or Lease Name Santa Fe Pacific
3. Address of Operator P.O. Box 537, Farmington, New Mexico 87401	9. Well No. 30
4. Location of Well UNIT LETTER <u>B</u> <u>410</u> FEET FROM THE <u>North</u> LINE AND <u>1930</u> FEET FROM THE <u>East</u> LINE, SECTION <u>29</u> TOWNSHIP <u>20N</u> RANGE <u>9W</u> NMPM.	10. Field and Pool, or Wildcat Red Mountain MV
15. Elevation (Show whether DF, RT, GR, etc.) 6496 (Re-Surveyed)	12. County McKinley

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to plug and abandon this well. We will clean out to TD of 973' and spot a 5 sx cement plug from bottom up. We will also spot a 3 sx plug at 500 feet and a 2 sx surface plug with a standard dry-hole marker.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mark E. Weidner TITLE Agent DATE 5/31/79

Original Signed by A. R. Kendrick

APPROVED BY \_\_\_\_\_ TITLE SUPERVISOR DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: