

NO. OF COPIES RECEIVED	8
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	6

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)


1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Hughes &amp; Hughes</b>	8. Farm or Lease Name <b>Santa Fe Tract 9</b>
3. Address of Operator <b>P. O. Box 152 Durango, Colorado</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>B</b> <b>480</b> FEET FROM THE <b>North</b> LINE AND <b>2267</b> FEET FROM THE <b>East</b> LINE, SECTION <b>15</b> TOWNSHIP <b>17N</b> RANGE <b>8W</b> NMPM.	10. Field and Pool, or Wildcat <b>Wildcat</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>6888 Ground</b>	12. County <b>McKinley</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled 7 7/8" hole to a depth of 1864' and penetrated the Gallup Formation  
Well was plugged and abandoned as follows:  
35 sz cement from 575' to 675'  
35 sz cement from 1600' to 1700'  
Plugged surface pipe  
Erected dry hole marker  
Cleaned and leveled location



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Emery C. Arnold TITLE Geologist-Agent DATE 6-21-66

Original Signed by Emery C. Arnold  
APPROVED BY \_\_\_\_\_ TITLE SUPERVISOR DIST. #3 DATE JUN 24 1966

CONDITIONS OF APPROVAL, IF ANY: