

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

February 12, 1986

Mr. Gavino Perez Tesoro Petroleum Corp. 8700 Tesoro Dr. San Antonio, TX 78286

M - 05 - 17N - 08WSanta Fe Railroad B #38 Re: Hanson #19 K-06-17N-08W K-06-17N-08W Hanson #21 Hanson #18 M - 06 - 17N - 08WHanson #43 M-06-17N-08W Hanson Federal #34 0-06-17N-08WSanta Fe Railroad #10 B-07-17N-08W D-07-17N-08W Santa Fe Railroad #22 F-07-17N-08W Santa Fe Railroad #24 Hospah Sand Unit #49 A-01-17N-09W Santa Fe Pacific Railroad #A-87 P-01-17N-09W A-12-17N-09W Santa Fe Railroad #54-L B-36-18N-09W Hospah Sand Unit #68 E-36-18N-09W Hospah Sand Unit #69 H-36-18N-09W Hospah Sand Unit #64 Hospah Sand Unit #70 L-36-18N-09W P-36-18N-09W Hospah Sand Unit #65

Dear Mr. Perez:

A letter, dated November 21, 1985, directed you to repair the referenced wells within 60 days. To date we have not received any Division C-103 forms showing intent to repair casing, nor has any remedial action commenced. You are hereby directed to submit forms C-103, and begin repairs on the referenced wells within 30 days. A form C-103 is enclosed for your reference.

Yours truly,

Carolyn J. Taplin Field Representative

for the second second

CJT/dj

xc: Prentiss Childs
UIC File
Operator File
Well File