

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	1
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <i>K-1883</i>
7. Unit Agreement Name
8. Farm or Lease Name <i>Ohwell</i>
9. Well No. <i>#2</i>
10. Field and Pool, or Wildcat <i>Chaco Wash-Mesa Verde</i>
12. County <i>McKinley</i>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator <i>Burwenkle &amp; Stanton &amp; Husky Energy, Inc.</i>
3. Address of Operator <i>124 Jackson N.E., Albuquerque, N.M., 87100</i>
4. Location of Well UNIT LETTER <i>C</i> <i>495</i> FEET FROM THE <i>N</i> LINE AND <i>2145</i> FEET FROM THE <i>W</i> LINE, SECTION <i>28</i> TOWNSHIP <i>20N</i> RANGE <i>9W</i> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <i>Record of plugging</i> <input checked="" type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>


17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

*Run tubing into hole to 500 feet and pumped 5 sacks of Cement; pulled tubing to 250 feet and pumped 5 sacks of Cement; pulled tubing and set well marker at well location using 2 sacks of cement. Cleaned lease and obliterated pits.*

*INSPECTED 11-7-74*

*OK.*

*C.S.*



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *R.J. Donlon* TITLE *Partner* DATE *Oct. 26, 1974*

APPROVED BY *Emmy Clavel* TITLE *SUPERVISOR DIST. #3* DATE *NOV 7 1974*

CONDITIONS OF APPROVAL, IF ANY: