

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Burwinkle, Scanlon & Husky Energy Inc.		5. State Oil & Gas Lease No. K-1883
3. Address of Operator Box 388 Aztec, New Mexico 87410		7. Unit Agreement Name
4. Location of Well UNIT LETTER C 825 FEET FROM THE North LINE AND 2145 FEET FROM THE West LINE, SECTION 28 TOWNSHIP 20N RANGE 9W NMPM.		8. Farm or Lease Name N.M. State
15. Elevation (Show whether DF, RT, GR, etc.)		9. Well No. OH Well No. 6
16.		10. Field and Pool, or Wildcat Chaco Wash MV
		12. County McKinley


Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well plugged and abandoned as follows:

Set 15 sack plug from 545 feet to 485 feet. Filled hole with drilling mud. Placed 5 sacks cement at surface. Set surface marker. Cleaned and leveled location.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.
BURWINKLE, SCANLON & HUSKY ENERGY INC.

SIGNED Neel Reynolds TITLE Agent DATE April 3, 1972

Original Signed by A. R. Kendrick

APPROVED BY _____

PETROLEUM ENGINEER DIST. NO. 3

DATE APR 3 1972

CONDITIONS OF APPROVAL, IF ANY: