Form	9-331
(May	1963)

1.

DEPARTMENT OF THE INTERIOR (Other instructions on re-GEOLOGICAL SURVEY

rem approved, redget Bureau No. 42-R1424. 5. LEASE SESIGNATION AND SERIAL NO.

Fed. 1. 0557379 6. IF INDIAN, ALLOTTEE OR TRIBE NAME

020200101121								
	SUNDRY	NICTICES	עוע א	DEDODTS	$\triangle N$	//EIIC		
	ז אטאטענ	NOTICES	MINU	KELOKIS	O14	YY L L L J		

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT" for such proposals.)

7. UNIT AGREEMENT NAME

OIL GAS WELL 2. NAME OF OPERATOR George R. Jones & W. H. Poscheo

8. FARM OR LEASE NAME

3. ADDRESS OF OPERATOR 1620 Michita Plaza Bldg. were wo. a 1

ichita Kansas

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

At surface

10. FIELD AND POOL, OR WILDCAT

At surface 1980' FSL & 1980' FEL

OTHER

C., T., R., M., OR BLK. AND SURVEY OR AREA 31 - T19N - R12W

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO.

12. COUNTY OF PARISH 13. STATE

Gr. 6529 KB 6541

16.

(Other)

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO: PULL OR ALTER CASING TEST WATER SHUT-OFF MULTIPLE COMPLETE FRACTURE TREAT ABANDON* SHOOT OR ACIDIZE X REPAIR WELL CHANGE PLANS

WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING

REPAIRING WELL ALTERING CASING ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

Plug and abandon 5/30/68 per instrs. Ir. Phil McGrath

1600 to TD 490 to 610 surface

32 sx.

20 sx. 10 sx

JUN.

Location has been properly marked and leveled.

foc. impeted 5-30-68 by

18. I hereby certify that the foregoing is true and correct

TITLE Geologist

(This space for Federal or State office use)

A SONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

MAY 30 1968

*See Instructions on Reverse Side

P. T. McGRATH

^{17.} DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*