

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator <i>Burwable &amp; Sealeon and Husky Energy, Inc.</i>	5. State Oil & Gas Lease No. <i>K-1883</i>
3. Address of Operator <i>124 Jackson N.E., Albuq., N.M. 87100</i>	7. Unit Agreement Name
4. Location of Well UNIT LETTER <i>A</i> <i>495</i> FEET FROM THE <i>N</i> LINE AND <i>495</i> FEET FROM THE <i>E</i> LINE, SECTION <i>28</i> TOWNSHIP <i>20N</i> RANGE <i>9W</i> NMPM.	8. Farm or Lease Name <i>Chewell</i>
	9. Well No. <i># 11</i>
	10. Field and Pool, or Wildcat <i>Chico Wash-Mesa Verde</i>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <i>McKinley</i>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <i>Record of plugging</i> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

*Ran tubing into hole to 355 feet and set 100 ft cement plug at bottom of hole, pulled tubing after filling hole with mud. Set marker at well location using 2 sacks of cement. Cleaned lease and obliterated pits.*

*INSPECTED 11.7.74 O.K.*

*C.G.*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>R.D. Sealeon</i>	TITLE <i>Partner</i>	DATE <i>Oct 26, 1975</i>
APPROVED BY <i>Creedy C. Cunniff</i>	TITLE <i>SUPERVISOR DIST. #3</i>	DATE <i>NOV 7 1974</i>
CONDITIONS OF APPROVAL, IF ANY:		