

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO B7410 (505) 334-6178

February 12, 1986

Mr. Gavino Perez Tesoro Petroleum Corp. 8700 Tesoro Dr. San Antonio, TX 78286

Santa Fe Railroad B #38 Re: M-05-17N-08WHanson #19 K-06-17N-08W Hanson #21 K-06-17N-08W Hanson #18 M - 06 - 17N - 08WHanson #43 M-06-17N-08WHanson Federal #34 0-06-17N-08WSanta Fe Railroad #10 B-07-17N-08W Santa Fe Railroad #22 D-07-17N-08W -Santa Fe Railroad #24 F-07-17N-08W Hospah Sand Unit #49 A-01-17N-09W Santa Fe Pacific Railroad #A-87 P-01-17N-09W Santa Fe Railroad #54-L A-12-17N-09W Hospah Sand Unit #68 B-36-18N-09W Hospah Sand Unit #69 E-36-18N-09W Hospah Sand Unit #64 H-36-18N-09W Hospah Sand Unit #70 L-36-18N-09W Hospah Sand Unit #65 P-36-18N-09W

Dear Mr. Perez:

A letter, dated November 21, 1985, directed you to repair the referenced wells within 60 days. To date we have not received any Division C-103 forms showing intent to repair casing, nor has any remedial action commenced. You are hereby directed to submit forms C-103, and begin repairs on the referenced wells within 30 days. A form C-103 is enclosed for your reference.

Yours truly,

Carolyn J. Taplin Field Representative

CJT/dj

xc: Prentiss Childs
UIC File
Operator File
Well File