Form 3160-5

## UNITED STATES

	FORM APPROVED			
	ار ا	Bodget Bur	eau No.	1004-0135
RECEA		Expires:	March	31, 1993

June 1990)	DEPARTMENT OF THE INTERIOR	Bedget Bureau No. 1004-0135
	BUREAU OF LAND MANAGEMENT RECEN	Expires: March 31, 1993 Va. Dase Designation and Serial No.
	> DL	$N^{\prime\prime}$ 12335
Do not us	se this form for proposals to drill or to deepen or reentry to a different lestroom.	6. If Indian, Allottee or Tribe Name
		•
	SUBMIT IN TRIPLICATE	TON Unit of CA. Agreement Designation
1. Type of Wel		·
Oil Well	Gas Well Other	8. Well Name and No.
2. Name of Op	. 0.7 1 0	South Hospah Unit #40
3. Address and	ion Oil & Gas Corp. 713-469-9664 Telephone No.	9. API Well No.
8223	Willow Place South Ste 250 Houston, Texas 77070	10. Field and Pool, or Exploratory Area
4. Location of	Well (Footage, Sec., T., R., M., or Survey Description)	R. Hospah /cpw. Sd.
2420'	FNL & 1650' FEL Sec. 12, 17N, 9W	11. County or Parish, State
		McKinley County, NM
12. C	HECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR	T, OR OTHER DATA
7	TYPE OF SUBMISSION TYPE OF ACTION	
[	X Notice of Intent	Change of Plans
r	Recompletion	New Construction
L	Subsequent Report OCT 3 1992 Plugging Back	Non-Routine Fracturing
[	Final Abandonment New LCON. DIV. Casing Repair  Altering Casing	Water Shut-Off Conversion to Injection
	DIST 3 Other Plug and abandon	Dispose Water
	Dioi: 3	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
3. Describe Pro give sub	posed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting surface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	any proposed work. If well is directionally drille
the fo	ion Oil & Gas Corp. request permission to plug and abandon the ollowing procedure:	is well by using
		TI 100/ 0 03
-,	TIH w/open-end 2 7/8" tbg to TD (1630'). Spot 24 sx Class "B up to ±1200', reverse ciruclate until clean. WOC*2 hrs.	$^{\circ}$ cmt w/2% Call <sub>2</sub> , pull
2)	Tag TOC, spot 9 ppg mud from TOC to $\pm 620$ '. TOH.	<i>52</i>
3)	TIH w/pkr & tbg, set pkr @ ±225'. Perforate 4 squeeze holes	
	Class "B" cmt w/2% CaCl <sub>2</sub> . Displace cmt w/9ppg mud to ± <del>525</del> . until clean, reset pkr, WOC 2 hrs.	Reverse circulate
4)	Perf 4 sqz holes @ 275'. Pump 20 sx Class "B" cmt w/2% CaClo	. Displace cmt with
	ndd to bun o'i pkr. Move pkr up 1 jt, reverse circulate w/ mū	d until clean. LD
5)	tbg & pkr. WOC 2 hrs. Perf 4 sqz holes @ 120'. Pump 50 sx Class "B" cmt via csg to	f:11 :
	annulus. Top off csg and annulus as necessary.	illi CSG and ITS
6) (	Cut off csg and weld on plate with 4" X 4' marker post.	
7,7	Clean location.  SEE ATTACHED FOR	
	CONDITIONS OF APPROVAL	
4. I hereby cert	ify that the foregoing is true and correct	
Signed 2	Title Production Regulatory Supv	— A₱₽₱Ġ₩₽D
	or Federal or State office use)	AS AMENDED
Approved by Conditions of	approval, if any:	0°CT 0 6 1992 D
		OOI & AVOIC D

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, licitious or fraudulent statements or representations as to any matter within its jurisdiction. \*See Instruction on Reverse Side