

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

30-031-20183

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.		7. Unit Agreement Name
OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Convert SI Gas Well to Injection		8. Farm or Lease Name SFP - RR
Name of Operator Tenneco Oil Company		9. Well No. 10
Address of Operator Suite 1200 Lincoln Tower Bldg. - Denver, Colo		10. Field and Pool, or Wildcat Lone Pine Dakota "D"
Location of Well UNIT LETTER <u>B</u> <u>800</u> FEET FROM THE <u>North</u> LINE AND <u>3500</u> FEET FROM THE <u>West</u> LINE, SECTION <u>13</u> TOWNSHIP <u>17</u> RANGE <u>9</u> NMPM.		12. County McKinley
15. Elevation (Show whether DF, RT, GR, etc.) 7010 GR		

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <u>Convert to Gas Injection</u> <input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF: PLUG AND ABANDON <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Move in service unit, kill well with water, pull tubing, Perforate Dakota "D" Sand 2720' - 22 and 2728' - 34' with 2 JSPF. Run 3-1/2" OD tubing with packer set at + 2700'. Acidize w/500 gals. 15% HCL, swab and flow well to clean up. Hook up well for injection.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>G. A. Ford</u>	TITLE <u>Sr. Production Clerk</u>	DATE <u>3/13/72</u>
Original Signed by A. R. Kendrick		
APPROVED BY _____	TITLE <u>PETROLEUM ENGINEER DIST. NO. 3</u>	DATE <u>MA</u>
CONDITIONS OF APPROVAL, IF ANY:		