

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65
30-031-20183

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dual (oil & Gas)	7. Unit Agreement Name Lone Pine Dakota "D" Unit
2. Name of Operator Tenneco Oil Company	8. Farm or Lease Name
3. Address of Operator Suite 1200 Lincoln Tower Bldg. - Denver, Colo.	9. Well No. 12
4. Location of Well UNIT LETTER B, 800 FEET FROM THE North LINE AND 3500 FEET FROM THE West LINE, SECTION 13 TOWNSHIP 17 RANGE 9 NMPM.	10. Field and Pool, or Wildcat Dakota
15. Elevation (Show whether DF, RT, GR, etc.) 7010 GR	12. County McKinley

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:


SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Convert to Dual	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Move in completion unit, pull tubing, set plug @ \pm 2700', perforate "A" zone 2560'-2576' w/2 JSPF, Frac formation, swab, remove plug, install packer @ \pm 2700', run tubing. Produce "D" zone through tubing and "A" zone through annulus.

Reference NMOCC Order No. R-4341



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W L Shaver TITLE Sr. Production Clerk DATE 7/7/72
APPROVED BY A. R. Kendrick TITLE PETROLEUM ENGINEER DIST. NO. 3 DATE JUL 24 1972
CONDITIONS OF APPROVAL, IF ANY: