

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

N00-C-14-20-4305

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo-Allotted

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

BSK Edna

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Lone Pine Dakota "D"

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

8. T17N, R8W

12. COUNTY OR PARISH 13. STATE

McKinley

N. Mexico

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Basin Fuels, Inc.

3. ADDRESS OF OPERATOR

152 Petroleum Center Bldg., Farmington, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

2200' FNL & 1650' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7045 K.B.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐


ALTERING CASING ☐

ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

9-23-74: Rig up csg. pulling unit. Ran tbg. to 1824. Spot 35 sk. cement plug over Hospah perfs. 1807-11 from 1483 ft. to 1824 ft. Pull tbg. Install csg. jacks, 9-24-74; Shot pipe off at 1042 ft. Pull 5½" csg. Run tbg. to 1142 ft. Spot 35 sk. cement plug from 956 to 1142 ft. Pull tbg. 9-25-74. Spot 15 sk. cement plug in surface. Install dry hole marker. Well P & A 9-25-74. Location will be cleaned and ready for inspection by 10-10-74. 5½" csg. stub at 1042 ft. Cement spotted from 956 ft. to 1142 ft. Well plugged due to being non-productive in Hospah Zone and reserves depleted in Dakota "D" Zone.



18. I hereby certify that the foregoing is true and correct

SIGNED

Jack D. Cook

TITLE

Agent

DATE

9-30-74

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side