

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
USA N. M. 7772	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - II" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	3
3. Address of Operator	8. Farm or Lease Name
P. O. Box 51, Farmington, New Mexico 87401	Papenthin
4. Location of Well	9. Well No.
UNIT LETTER 3, 1650' FEET FROM THE North LINE AND 1980' FEET FROM	1
THE West LINE, SECTION 26 TOWNSHIP 19N RANGE 5W NMPM.	10. Field and Pool, or Wildcat
	Wildcat
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
6864 KB	McKinley

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon, clean and level location. Erect dry hole marker.

Verbal approval to set plugs as follows:

# 1. 2792' - 3000'	60 sx
# 2. 1316' - 1650'	60 sx
# 3. 896' - 1016'	36 sx
# 4. 50' - 125'	25 sx
# 5. 9L - 5'	and erect dry hole marker

Recover 4 1/2" casing where possible.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Don Wilson TITLE Sup. DATE 3-7-78

APPROVED BY AK Kendrick TITLE SUPERVISOR DIST. #3 DATE MAR 7 1978

CONDITIONS OF APPROVAL, IF ANY: