ž.,

## UNITED STATES

7 7

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	USA N. M. 7772
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME 3
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas other	Paperthin 9. WELL NO.
2. NAME OF OPERATOR	7
John J. Staver	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	
P. O. Box 51, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 1650 JNL, 1980 JUL
below.) AT SURFACE:	Sec. 26 - J19N- R5W  12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	McKinley N. M.
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6864_KB
TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertined Propose to plug and abandon, clean and level Verbal approval to set plugs as follows:	nt to this work.)*
# 1. 2792' - 3000' 60 A # 2. 1316' - 1650' 60 A	
# 3. 896 <sup>7</sup> - 1016 <sup>8</sup> 36 A	
# 4. 50' - 125' 25 A	$\mathbf{x}$ $\mathbf{\hat{f}}$ $\mathcal{N}$ $\mathcal{N}$
	t dry hole marker
Recover 42" casing where possible. Subsurface Safety Valve: Magu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	3-7-78
SIGNED LEGICAL TITLE	DATE 30/0/0
(This space for Federal or State of	
CONDITIONS OF APPROVAL, HANK	DATE
	NMOCCI

en for

\*See Instructions on Reverse Side