

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-B1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM-2772

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

9. WELL NO.

10. FIELD AND TOOL, OR WILDCAT

11. SEC. T. R. M. OR BLK. AND
SURVEY OR AREA

12. COUNTY OR PARISH 13. STATE

McKinlay New Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Eastern Petroleum Corporation

3. ADDRESS OF OPERATOR

PO Box 291, Carri, Illinois 62821

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surfaceNW $\frac{1}{4}$ NW $\frac{1}{4}$ Sec. 26, T-19-N, R-5-W, NMPM

14. PERMIT NO.

Issued 1-6-73

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

6580' RKB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data.

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*


(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*This well was P & A on December 10, 1974, and pits filled
Location leveled & dry hole marker erected

1. Plug was run T. D, 3065' to 2980' through 2 3/8" tubing
2. Plug 100' plug on 5 1/2" casing stub @ 1950'
3. Plug 1750' to 1850' through 5 1/2" casing
4. Plug 300' to 400' through 5 1/2" casing
5. 10 sacks in surface & dry hole marker erected

Location ready for inspection

18. I hereby certify that the foregoing is true and correct.

SIGNED



TITLE

Manager

DATE

January 5, 1975

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JAN 22 1975