

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER <u>Core Test</u>		5. LEASE DESIGNATION AND SERIAL NO. <u>44-055231</u>
2. NAME OF OPERATOR <u>Gulf Oil Corporation</u>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <u>Box 67, Hobbs, New Mexico 88240</u>		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) <u>At surface</u> <u>1930' N. & W., Section 20, 18-N, 5-W</u> <u>PLEASE CONSIDER THIS INFORMATION CONFIDENTIAL</u>		8. FARM OR LEASE NAME <u>Richardson "Federal"</u>
14. PERMIT NO.		9. WELL NO. <u>1</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>7238' RT</u>		10. FIELD AND POOL, OR WILDCAT <u>Core Test</u>
		11. SEC., T., R. & OR N.E.K. AND SURVEY OF AREA <u>Sec 20, 18-N, 5-W</u>
		12. COUNTY OF ORIGIN: STATE <u>McKinley New Mexico</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) <u>Plugged & Abandoned</u>	
(Other) ☐		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4379' TH.

Young Drilling Company spudded 7-7/8" hole at 3:00 PM, October 6, 1971. Reached TD of hole at 4379' at 11:00 PM, October 12, 1971. No indication of commercial production. Obtained permission from Mr. Ed Schmidt with L. S. S. Co. in Durango and plugged and abandoned as follows: Spotted 33 sack cement plug No. 1 from 3970' to 4070'; 13 sack cement plug No. 2 from 3250' to 3350'; 33 sack cement plug No. 3 from 2010' to 2110'; 16 sack cement plug No. 4 from 75' to 125' and 50' plug No. 5 from 50' to surface. Installed dry hole marker. Plugged and abandoned October 13, 1971.

ILLEGIBLE

OCT 19 1971
OIL CON COM
DIST 3

18. I hereby certify that the foregoing is true and correct

SIGNED <u>C. D. BORLAND</u> (This space for Federal or State office use)	ORIGINAL SIGNED BY <u>C. D. BORLAND</u> TITLE <u>Area Production Manager</u>	DATE <u>October 14, 1971</u>
APPROVED BY _____ CONDITIONS OF APPROVAL, IF ANY: _____	TITLE _____ DATE _____	

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, or all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of abandonment; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1967
GPO 837-499
837-851

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

PROPOSAL FOR ABANDONMENT	REPORT OF ABANDONMENT	REPORT OF PRODUCTION	REPORT OF OTHER DATA
☐	☐	☐	☐

1. NAME OF OPERATOR

2. ADDRESS OF OPERATOR

3. LOCATION OF WELL (Report location exactly, and in accordance with any State requirements. See space below.)

4. DEPTH OF WELL (Report depth exactly, and in accordance with any State requirements. See space below.)

5. TYPE OF WELL (Check appropriate box)

6. DATE OF OPERATION

7. NAME OF INSPECTOR

8. ADDRESS OF INSPECTOR

9. DATE OF INSPECTION

10. NAME OF STATE OFFICE

11. ADDRESS OF STATE OFFICE

12. DATE OF SUBMISSION

13. NAME OF FEDERAL OFFICE

14. ADDRESS OF FEDERAL OFFICE

15. DATE OF RECEIPT

U.S. GOVERNMENT PRINTING OFFICE: 1967
GPO 837-499
837-851

1. NAME OF OPERATOR

2. ADDRESS OF OPERATOR

3. LOCATION OF WELL (Report location exactly, and in accordance with any State requirements. See space below.)

4. DEPTH OF WELL (Report depth exactly, and in accordance with any State requirements. See space below.)

5. TYPE OF WELL (Check appropriate box)

6. DATE OF OPERATION

7. NAME OF INSPECTOR

8. ADDRESS OF INSPECTOR

9. DATE OF INSPECTION

10. NAME OF STATE OFFICE

11. ADDRESS OF STATE OFFICE

12. DATE OF SUBMISSION

13. NAME OF FEDERAL OFFICE

14. ADDRESS OF FEDERAL OFFICE

15. DATE OF RECEIPT