

NO. OF COPIES RECEIVED	
DISTRIBUTION	5
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P & A		7. Unit Agreement Name
2. Name of Operator Northern Minerals, Inc.		8. Farm or Lease Name SFPRR Co.
3. Address of Operator P. O. Box 2182, Santa Fe, New Mexico 87501		9. Well No. 4
4. Location of Well UNIT LETTER M , 660' FEET FROM THE South LINE AND 660' FEET FROM THE West LINE, SECTION 33 TOWNSHIP 17N RANGE 7W NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 6726 Ground Level		12. County McKinley

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>	
ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was plugged and abandoned on May 12, 1973. Cement plugs were set at the following intervals:

50' on bottom, 3030' to 3082'.
100' across top Dakota "D" - 2802' to 2920'.
150' across Massive Gallup - 1825' to 1975'.
100' across base Point Lookout - 750' to 850'.
Surface plug - 5 sacks

A dry hole marker will be erected, the pits filled and the location restored.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lloyd Davidson TITLE President DATE May 16, 1973

APPROVED BY Ernest L. Ames TITLE SUPERVISOR DIST. DATE 5-6-74

CONDITIONS OF APPROVAL, IF ANY:

NEW MEXICO OIL CONSERVATION COMMISSION
1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

Northern Minerals Inc
Po Box 2182
Santa Fe New Mex 87501

Re: Plugging Reports



Gentlemen:

Form C-103, Notice of Intention to Plug, your SE PRR 4
Lease Well No.

M-33-17N-7W was approved 6-18-73. Your
Unit S-T-R

subsequent notice of plugging cannot be approved until a commission representa-
tive has made an inspection of the location to see:

- (1) all pits have been filled and leveled;
- (2) a steel marker, 4" in diameter and approximately 4' above mean ground level, must be set in concrete, this marker must have the quarter-quarter section or unit designation, section, township and range numbers, which shall be permanently stenciled or welded on the marker;
- (3) the location shall be cleared and cleaned of all junk;
- (4) the dead man wires must be cut.

The above are the minimum requirements.

Please notify us by filling in the blank form below when this work has been done so that our representative will not have to make more than one trip to the location.

OIL CONSERVATION COMMISSION

By Querry C. Lunsford

Fill in below and return:

SE PRR 4 M-33-17N-7W is ready for your inspection and
Lease Well No. Unit S-T-R
approval.

LOCATION IN SP. O.K.

Northern Minerals, Inc
Operator
David Davidson, President
Name and title

10-5-73