

NO. OF COPIES RECEIVED	7
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	2
LAND OFFICE	1
OPERATOR	2

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
NM 662	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name
2. Name of Operator		Hospah Sand Unit
3. Address of Operator		8. Farm or Lease Name
1776 Lincoln St., Suite 1012, Denver, Colorado 80203		Hospah Sand Unit
4. Location of Well		9. Well No.
UNIT LETTER G, 2310 FEET FROM THE North LINE AND 1650 FEET FROM THE East LINE, SECTION 36 TOWNSHIP 18N RANGE 9W NMPM.		10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
GL 7144'; KB 7155'		McKinley

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well, drilled to the Dakota 'D' zone was incapable of producing at a commercial oil or gas rate from either the Dakota 'D' or the Upper Hospah.

Tesoro plugged and abandoned this well according to the following procedure:

1. Spotted a 30 sx. cement plug accross perfs. (perfs. at 1816' - 1820')
2. Shot casing off at 1350' from surface. Recovered 1350' of 5 1/2" casing (42 joints, 14# K-55, 8rd., ST&C casing).
3. Spotted a 30 sx. plug across 5 1/2" casing stub.
4. Spotted 25 sx. cement plug across bottom of surface casing.
5. Set 15 sx. on surface casing and installed a dry hole marker according to state regulations.
6. Completed procedure 9/19/74. Will be ready for inspection on November 1-1974.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>L. C. Marguaret</u>	TITLE <u>District Engineer</u>	DATE <u>10/2/74</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DIST. 53</u>	DATE <u>12-17-74</u>
CONDITIONS OF APPROVAL, IF ANY:		

