

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

API # (assigned by OCD)

5. 30-031-20445
Lease Number

Fee

6. State Oil & Gas Lease #

7. Lease Name/Unit Name
Santa Fe Pacific

8. Well No.
#116

9. Pool Name or Wildcat

10. Elevation:

1. Type of Well
OIL

2. Name of Operator
Geo Engineering

3. Address & Phone No. of Operator

P.O. Box 2966
Santa Fe, NM 87505

990/5 1650/w

4. Location of Well, Footage, Sec., T, R, M
Sec. 22 T-20-N, R-9-W, NMPM, McKinley County
Unit N, SE/4SW/4

Type of Submission

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment

Type of Action

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other -

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

A-Plus Well Service, contractor, will plug and abandon said well according to the attached procedure prepared by NMOCD.

This work will be in accordance with State of New Mexico Contract No. 98-521.25-059.

RECEIVED
JAN 22 1998

OIL CON. DIV.
DIST. 3

SIGNATURE William F. Clark Contractor

December 30, 1997

(This space for State Use)

Approved by

Johnny Robinson

DEPUTY OIL & GAS INSPECTOR, DIST. #3

Title

Date JAN 22 1998

COMPANY

Geo Engineering

PROPERTY NAME

Santa Fe Pacific

WELL NO.

116

DATE

LOCATION (ULSTR)

N-22-20N-09W

FOOTAGE

API NO.

POOL

No Csg?


Couldn't find well

CASING RECORD:

55X. plug @ 425'

6 1/4 Hole

Never completed



Open Hole?

well Not Found

| | | | | |
|--|----------------------------------|-----------------------------------|---------|-----------------|
| COMPANY Geo Engineering | | PROPERTY NAME Sante Fe Pacific | | WELL NO. 116 |
| DATE | LOCATION (ULSTR) N-22-20N-09W | | FOOTAGE | |
| API NO. | | POOL | | |
| <div style="border: 1px solid black; border-radius: 50%; padding: 10px; display: inline-block;">No CSG?</div> | | | | |
| Couldn't find well | | | | |
| CASING RECORD: | | | | |
| 5SX. plug @ 425' | | | | |
| 6 1/4 Hole | | | | |
| Never completed | | | | |
| <ol style="list-style-type: none">1. Determined depth2. If depth is 300' or more continue with procedure if not move in rig & clean out hole to 300'3. GIH with slick line to 425' & spot a 200' plug @ 425'.4. POH to 30' + circ. cement to the surf.5. Install dry hole marker | | | | |
| <div style="text-align: right;">6 1/4 hole 425'</div> <div style="text-align: center;">Open Hole</div> | | | | |