

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Sundry Notices and Reports on Wells

1. Type of Well OIL	5. Lease Number NM-12201
2. Name of Operator NERDLIHC	6. If Indian, All. or Tribe Name
3. Address & Phone No. of Operator C/O NMOCD, 1000 Rio Brazos Road, Aztec, NM 87410	7. Unit Agreement Name
Location of Well, Footage, Sec., T, R, M 330' FNL 330' FEL, Unit A, Section 24, T-16N, R-10W	8. Well Name & Number Mareline #1
	9. API Well No. 6 30-031-20448
	10. Field and Pool
	11. County & State McKinley County, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action
☐ Notice of Intent	☒ Abandonment
☒ Subsequent Report	☐ Recompletion
☐ Final Abandonment	☐ Plugging Back
	☐ Casing Repair
	☐ Altering Casing
	☐ Other -
	☐ Change of Plans
	☐ New Construction
	☐ Non-Routine Fracturing
	☐ Water Shut off
	☐ Conversion to Injection

13. Describe Proposed or Completed Operations

This well was plugged under NMOCD Contract #00-521-25-205 per attached work report.

14. I hereby certify that the foregoing is true and correct.

Signed William F. Clark Title Contractor Date 1/8/01
William F. Clark

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____
CONDITION OF APPROVAL, if any:

COPIED FOR RECORD

AN 17 2001

NMOCD

Rig No

Date _____

Well No. 4

Location

Company

FROM	TO	DESCRIPTION OF OPERATION
		Oct 30, 2000 Wireline Bruce Martin W/MUCD - Run 4 1/2" C.R to 1633' - 2 down heavy pump, Set CIBPC 1635' (Plugged)
Mon 11-13-00		R-U CUD & P-T #104' T.H with coiled YB9 & TAG CIBP @ 1,642' LOAD The Hole & CIRCULATE CLEAN with 14 BBLS WATER. TEST CSG TO 500' HOLD 5 min OK. Plug #1 mix & Pump 12 SKS cement, From 1,642' to Tag @ 1,484'. POOH with YB9 TO 955'. LOAD The Hole with 2 BBLS WATER. Plug #2 mix & Pump 20 SKS cement, From 955' to Tag @ 691'. POOH with YB9 TO 500'. CIRCULATE The Hole with 11 BBLS WATER. POOH. R-D EQUIP. MAL. BRUCE MARTIN W/AMACO ON LOC.
Mon 11-20-00		T.H with wireline & TAG Tag @ 699'. Pull UP Hole & Perforate 2-HSC Holes @ 141' POOH. HENRY VILLANUEVA W/AMACO ON LOC.
Tue 11-30-00		Break Good CIRCULATION out The B-H with 60 BBLS WATER. Plug #3 mix & Pump 44 SKS cement, From 141' with 900 cement Returns out The B-H. HENRY VILLANUEVA W/AMACO ON LOC.
Fri 12-1-00		CUT OFF Well HEAD, INSTALL marker with 5 SKS cement All for the MARKER 4 1/2" & SURF CSG @ SURF.
Dec 02/00		Removed pumping unit, 2 TANKS 1- Separator.

Fuel & Motor Oil _____ Water Hauled _____
Rental Equipment _____ Cement Retainers _____
Cementing P-#1-12 SKS P-#2-20 SKS P-#3-47 SKS marker 5 SKS - 8/5 SKS
Wireline 4 1/2" C.R. 4 1/2" 8/16" Well CIP 2-HSC Holes 2 141' bid - 100 SK

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	Bill Clark	45		
Operator	Bob Stuart	131		
Helper	Span Stuart	161		
Helper				
Helper				