

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
09725	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Zenith Energy Corp.		SFPRR
3. Address of Operator		9. Well No.
P. O. Box 1038, Kilgore, Texas 75662		21
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>H</u> <u>990</u> FEET FROM THE <u>East</u> LINE AND <u>1750</u> FEET FROM		Hospah
THE <u>North</u> LINE, SECTION <u>29</u> TOWNSHIP <u>16N</u> RANGE <u>6W</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
6446'		McKinley

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
		OTHER <u>Complete previous drilled well</u> <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Start drilling operation 12-22-76
2. Suspend 12-23-76
3. Resume 12-27-76
4. 1-11-77 - Set 4 1/2" csg. @ 771'
5. 8-18-80 - Ran G/R-N Log
6. 10-18-80 - Rig up and circulate hole clean
7. 10-18-80 - Perf. 754' - 768', ran directional survey
8. 10-27-80 - Ran rods and tubing @ 736'
9. 10-30-80 - Put on production
10. 11-2-80 - Put on test



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Gary Blanks Gary Blanks TITLE Representative

DATE 11/24/80

Original Signed by FRANK T. CHAVEZ

SUPERVISOR DISTRICT # 3

DEC 4 1980

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: reamine & log, deviation, and C-105