

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 47-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 7510-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal Tinian 26

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

SEC. 26, T19N, R5W

12. COUNTY OR PARISH

McKinley

13. STATE

N.M.

1. OIL WELL GAS WELL OTHER Dry Hole

2. NAME OF OPERATOR

Dome Petroleum Corporation

3. ADDRESS OF OPERATOR c/o Minerals Management Inc., Suite 105,

501 Airport Drive, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

960' FSL, 430' FWL, SEC. 26, T19N, R5W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6639' GR 6654' KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2-23-77

Operator proposes to abandon well as follows:

Plug No. 1	8400'-8550'	(150')	75 sacks (Hermosa)
Plug No. 2	6300'-6450'	(150')	75 sacks (Glorietta)
Plug No. 3	5190'-5390'	(200')	100 sacks (Entrada)
Plug No. 4	4060'-4160'	(100')	50 sacks (Intermediate Casing Shoe)
Plug No. 5	-----	(100')	50 sacks (Casing Stub)
Plug No. 6	1825'-1875'	(150')	75 sacks (Pt. Lookout)(if exposed)
Plug No. 7	100'- 200'	(100')	50 sacks (Surface Casing Shoe)
Plug No. 8	0'- 20'	(20')	10 sacks (Surface)

Dry hole marker will be erected and pit fenced.

Location will be cleaned to satisfaction of BLM.

Verbal approval received from Jerry W. Long, USGS, Durango, Colorado,
at 10:45 p.m., February 23, 1977, by W. E. Landry.

CONFIDENTIAL

FEB 23 1977

18. I hereby certify that the foregoing is true and correct

SIGNED

J. Arnold Swell

TITLE

Area Manager

Minerals Management Inc.

DATE

February 24, 1977

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side