

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-31-20522
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Synergy Operating LLC		6. State Oil & Gas Lease No. V-1621
3. Address of Operator P.O.Box 5513, Farmington, NM 87499		7. Lease Name or Right Agreement Name: PWU (16719)
4. Well Location Unit Letter <u>H</u> : <u>2310</u> feet from the <u>North</u> line and <u>330</u> feet from the <u>East</u> line Section <u>16</u> Township <u>19N</u> Range <u>5W</u> NMPM McKinley County		8. Well No. 2
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 5690' RKB		9. Pool name or Wildcat Papers Well Entrada (49580)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT. <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

6/23/99:

MI RU Key Energy rig #8. Bleed well to workover pit.

6/24/99:

ND WH, NU BOP. LD 3-1/2" tbg. RIH w/ guage ring to 5150'. Set 7" CIBP @ 5134' on W/L. TIH, picking up, 2-3/8" workstring & tagged CIBP @ 5134'. Circ hole w/ FW. Attempt to Pressure Test Csg to 500#, had hole, injecting @ 1/4-BPM @ 500#. SION.

6/25/99:

Plug #1(Entrada): Spot 19-sxs Cl 'B' cmt from 5134-5034' on top of CIBP @ 5134'. Well still flowing after plug set. PUH to 4198'
Plug #2(Dakota): Spot 78-sxs Cl 'B' cmt + 2% CaCl₂ from 4198-3766', TOOH, WOC 4-Hrs, TIH & tag TOC @ 3766'. (Change in procedure approved by NMOCDD) Well still flowing after plug set. PUH to 2963'.

Plug #3(Gallup): Spot 78-sxs Cl 'B' cmt + 2% CaCl₂ from 2963-2563', PUH, WOC 4-Hrs, TIH & tag TOC @ 2563'. (Change in procedure approved by NMOCDD) Well quit flowing after plug set. TOOH. SION.

6/26/99:

TIH to 833'. Pressure tested Csg to 500# for 10-Minutes, Held OK.

Plug #4(Mesa Verde): Spot 29-sxs Cl 'B' cmt from 833-683'. PUH to 247'.

Plug #5(Surface): Circ 48-sxs Cl 'B' cmt from 247-Surface. TOOH. ND BOP. Dig cellar, cut-off WH 3' below Ground Level. Top off w/ 8-sxs Cl 'B' cmt. RD Key Energy rig #8. Install P&A marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Glen O. Papp TITLE Operations Manager DATE 7/6/99

Type or print name Glen O. Papp

Telephone No. 325-5449

APPROVED BY A. Villanueva

TITLE DEPUTY OIL & GAS INSPECTOR, DIST. 3

DATE SEP 21 2000

Conditions of approval, if any: