

SECRETARY

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

1000 RID BRAZOS ROAD AZTEC, NEW MEXICO B7410 (505) 334-6178

February 26, 1980

Mr. Gene Wilson Fairfax Exploration Incorporated 301 B Graceland, S. E. Albuquergue, NM 87108

Re: Bullseye #8

D-19-16N-9W

Dear Mr. Wilson:

Please file a sundry notice immediately, showing the following:

- 1. Spud date and time
- 2. Size and depth of surface hole
- 3. Size, weight, and amount of surface casing run
- 4. Kind and quantity of cement used to set surface pipe, where the top of the cement came to, and pressure test
- 5. Size of hole to present TD
- Present condition of hole stating fluid left in the hole and location of stuck pipe
- 7. Proposed plugging program

If we do not receive the above information within 30 days, we will docket a case for hearing in Santa Fe, calling Fairfax Exploration, to come forth and show cause why they should not be held in violation of the Rules and Regulations of the 0il Conservation Division and fined in accordance with Sec. 65-3-17 of NMSA 1953 Comp. We would also seek to cause you to plug the referenced well in an acceptable manner or we would plug the well ourselves and call on your bond to pay for it.

If you have any questions, please call

5rahs.

Frank T. Chavez
District Supervisor

FTC:dh

XC: Ernie Padilla

Assistant to the Attorney General

OCD, Santa Fe