

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. ---
7. Unit Agreement Name ---
8. Farm or Lease Name Lee 19
9. Well No. 1
10. Field and Pool, or Wildcat Marcellina Dakota
12. County McKinley

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
PETROLEUM DEVELOPMENT CORPORATION

3. Address of Operator
9720 B Candelaria, NE, Albuquerque, New Mexico 87112

4. Location of Well
UNIT LETTER C 1650 FEET FROM THE West LINE AND 330 FEET FROM
THE North LINE, SECTION 19 TOWNSHIP 16N RANGE 9W NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
7207 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>
	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.


TD 760'. Bit at 473', drill pipe stuck in hole--unable to pull.

Plug as approved by Frank Chavez 11-22-78:

Cement with 60 sx. to fill hole 473-760'.

Cement with 30 sx. for plug 50-150' *inside and outside of drill pipe.*

Set surface plug and marker, clean location and fill pits.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles W. Sanders TITLE Vice President DATE 11/24/78

APPROVED BY [Signature] TITLE SUPERVISOR DATE NOV 27 1978

CONDITIONS OF APPROVAL, IF ANY: