Form 9-331 Dec. 1973	Form Approved. Budget Bureau No. 42–R1
UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE 99 99 99 99 99 99 99 99 99 99 99 99 99
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME SHEET S
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME Building Solo of
2. NAME OF OPERATOR	es be of the of
Basin Fuels, Ltd. 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Franciscan Lake Mesa Verde
300 W. Arrington, Suite 300, Farmington, NM 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY
below.)	Sec 13, T20N, R6W & SERVE

S. ADDRESS OF OPERATOR	Franciscan Bake neba 19145
300 W. Arrington, Suite 300, Farmington, NM	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA LOGE : LEE
below.)	Sec 13, T20N, R6W & SER
AT SURFACE: 2310 FSL & 1650 FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	McKinley
AT TOTAL DEPTH:	14. API NO. 989 2 2 298 8
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO. Substitution of the control of the cont
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	l (PA) (PE-27
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	c shous burienoits and le shous burienoits and le shous burienoits ad le sugo complete redmun sultente change of the sultente change cha
TEST WATER SHUT-OFF	수 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
FRACTURE TREAT	d p
SHOOT OR ACIDIZE	bin
REPAIR WELL	(NOTE: Report results of multiple completion or zone
MULTIPLE COMPLETE	change of the transfer of the
CHANGE ZONES	ont to sell and the sell and th
ABANDON• □ □	
(other)	encitourder contenses encitourder less batgeons of the principal of the pr
	We we we will be a second of the second of t
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	all pertinent details, and give pertinent dates,
including estimated date of starting any proposed work. If well is displayed and true vertical depths for all markers and zones pertinent. Well was junked, plugged and abandoned as foll Plug #1 2050' - 2445' 100 sks Class Plug #2 315' - 515' 60 sks Class Plug #3 40' - 140' 30 sks Class Plug #4 0 - 30' 10	rectionally drilled, give subsurface locations and to this work.)* ल है है है है है है है है है
	The state of the s
Well was junked, plugged and abandoned as foll	Lows:
Plug #1 2050' - 2445' 100 sks Class	s "B" ಕಿರ್ನೈಕರ ಇಡಿದ್ದೇಕ್ಷ
Plug #2 315' - 515' 60 sks Class	3 "B" 0.5 5 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6
Plug #3 40' - 140' 30 sks Class	s "B" Sign Sign Sign Sign Sign Sign Sign Sign
Plug #4 0 - 30' 10 sks Class	B" GARAGE
Well P & A 9:00 PM 1-24-79. Install dry hole	marker skid rig to driff 2
replacement well.	Por Service of the property of
·	Service Survey of the Control of the
	The section of the se
	thing out the period of the pe
	The state of the s
	Jane 19 19 19 19 19 19 19 19 19 19 19 19 19
	ten de la constant de
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent. Well was junked, plugged and abandoned as foll Plug #1 2050' - 2445' 100 sks Class Plug #2 315' - 515' 60 sks Class Plug #3 40' - 140' 30 sks Class Plug #4 0 - 30' 10 sks Class Well P & A 9:00 PM 1-24-79. Install dry hole replacement well. Subsurface Safety Valve: Manu. and Type	Set @ FL

Subsurface Safety Valve: Manu. and Typ	pe			@v. <u>=</u>	# 5 E E	_ Ft.
18. I hereby certify that the foregoing is	s true and correct		ada of na ala d No em, so nortos	abecıl vo ab	etthe	
SIGNED Jack D. Cook	TITLE Agent	DATE _	1-25-79	201 3	2 E C T E	<u> </u>
***************************************	(This space for Federal or State office us	se)	100 100 100 100 100 100 100 100 100 100	10 X	15 E E	
APPROVED BY	TITLE	DATE	10 E 2 S	7=	\$35	j 1887 "
CONDITIONS OF APPROVAL, IF ANY:			i m mon mon mon mon mon mon mon mon mon mo	3	200	197
			0110 We 1 00 L	7 =	HE S	CO
			able ods ods	13		ī. 3
	*See-Instructions on Reverse Side			•	D 10	