Form 9-331 Dec. 1973	Budget/Bureau No. 42-R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NOO-C-14-20-4403 = 37 =
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	Navajo 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
SUNDRY NOTICES AND PERON ON WELLS	7. Divit Adictional Community of the Com
(Do not use this form for proposals to drill out de on or plot tack to a different reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME & BEE
	Noo Navajo
1. oil gas other	9. WELL NO. 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
2. NAME OF OPERATOR	5X 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
Easin Fuels, Ltd.	10. FIELD OR WILDCAT NAME Franciscan Lake-Mesa Verde
3. ADDRESS OF OPERATOR 300 W Arrington, Suite 300, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
300 W. Arrington, Suite 300, Farmington, NM 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA SESSE
below.)	Sec 13 T20N-R6W \$ 52.8
AT SURFACE: 2320' FSL & 1650" FEL	12. COUNTY OR PARISH 13. STATE McKinley NM
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	14 ADI NO
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
AUDOFOLIEUT DEDORT OF	6704/Ground 를 필요함됐
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	ရှိသည်။ တို့ ရှိရှိနှင့် ကျွန်းချိန်
TEST WATER SHUT-OFF U	관심 지수는 기가 가장 하는 경우 가장 그 그 것이 없다면 하는 것이 없다면 하는 것이 없다면 하는 것이 없다면 하는 것이다면
SHOOT OR ACIDIZE	
REPAIR WELL USE PULL OR ALTER CASING O	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
MULTIPLE COMPLETE	그 그는 사람들이 회원들이 가는 회원들은 기술이
CHANGE ZONES	그는 그는 그는 그는 요즘위한 그 중요한 한빛을 다양한다.
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	it to this work.)*
Drill 7 7/8" hole to TL 2765'/ Open hole logs indicate well to be non-commercial	
Log tops - Pictured Cliff - 430', Cliff House - 1625', Menefee - 1756'; and Point Lookout - 2722'. Plug and abandon well as follows:	
Plug #1 50 sacks Class "B" cement 4095 - 4195 year	
Plug #2 75 sacks Class "B" Cement 1495" - 1760 7 12	
Plug #3 50 sacks Class "B" C	Sement 330 = 500' 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
Plug #4 50 sacks Class "B" of Install dry hole marker. Fenced pits. Will resto	
specifications as soon as practical. Well P & A 4:15 AM 2-2-79	
Specifications as some as presented	물 그 그 그 그 그 물 수 있었다. 한 후 그를 중심된 그 그
Subsurface Safety Valve: Manu. and Type	Set @Ft.
	[[[]
18. I hereby certify that the foregoing is true and correct SIGNED Agent	DATE 2-5-79
(This apace for Federal or State office use)	
ANSW DID W. VERYARD PER DE DO SES PA	
APPROVED BY TITLE TITLE PROVINCE SUBJECT SUBJE	
CONDITIONS OF APPROVAL TO ANY:	
See Instructions on Reverse Side	

-*See Instructions on Reverse Side