

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Fairfax Exploration, Inc.	8. Farm or Lease Name Bullseye
3. Address of Operator 301-B Graceland S.E., Albuquerque, N.M. 87108	9. Well No. 11
4. Location of Well UNIT LETTER <u>L</u> , <u>1650</u> FEET FROM THE <u>South</u> LINE AND <u>910</u> FEET FROM THE <u>West</u> LINE, SECTION <u>18</u> TOWNSHIP <u>16 N</u> RANGE <u>9 W</u> NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 7257 Ground	12. County McKinley

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>


17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Plugged and abandoned 7:00 A.M. Sept. 25, 1979

Placed cement plugs as follows:

- 1. 1103' - 1050' 25 sx.
- 2. 530' - 430' 35 sx.
- 3. 50' - Surface 25 sx.

Placed 4 1/2" casing 5' above surface for permanent marker.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Charles Gholson</u>	TITLE <u>President</u>	DATE <u>Sept. 27, 1979</u>
Original Signed by CHARLES GHOLSON		
APPROVED BY	TITLE <u>DEPUTY OIL & GAS INSPECTOR, DIST. #3</u>	DATE <u>SEP 9 1980</u>
CONDITIONS OF APPROVAL, IF ANY:		