

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Santa Fe Pacific
9. Well No. 43
10. Field and Pool, or Wildcat Red Mountain MV
12. County McKinley

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-
2. Name of Operator Colorado Plateau Geological Services Inc
3. Address of Operator P. O. Box 537 - Farmington, N. M. 87401
4. Location of Well UNIT LETTER <u>B</u> , <u>420</u> FEET FROM THE <u>North</u> LINE AND <u>1940</u> FEET FROM THE <u>east</u> LINE, SECTION <u>29</u> TOWNSHIP <u>20N</u> RANGE <u>9W</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 6495 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to plug and abandond this well. Cement leaked around cement basket during completion attempts, and well is useless as injector or producer. Propose to clean out to 480' and plug from bottom up with 20SX regular cement which will give 280' of cement fill. We will set standard dry hold marker with a 2 5X plug at top.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Frank T. Chavez</u>	TITLE <u>President</u>	DATE <u>2-15-80</u>
APPROVED BY <u>Original Signed by FRANK T. CHAVEZ</u>	TITLE <u>SUPERVISOR DISTRICT #</u>	DATE <u>FEB 21 1980</u>
CONDITIONS OF APPROVAL, IF ANY:		